



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 74285  
Promised Date:  
24 JUL 24

### CUSTOMER WORK ORDER

WO #: 74285

Customer: 54995 - HENDERSON,  
PERRY - 812-550-7601

Tag:

Author: BH

Location: 0725 BH TO CLOSE

Stock #: 11408

Stock Desc: 2024 TT COACHMEN  
CATALINA SUMMIT SERIES 261BHS

Chassis #: 5ZT2CARB9RU043928

Serial #: 5ZT2CARB9RU043928

Mileage:

Licence:

Invoice #:

Date In: 22 JUL 24

Promised: 31 JUL 24

Date Sched:

Completed: 25 JUL 24

Warr. Date: 18 JUL 24

#### Job #1 - Warranty

COMPLAINT: STEPS ARE MOUNTED TO FAR OUT AND HITS  
DOOR WHEN CLOSING

CAUSE: Move steps inwards

CORRECTION: Inspected the steps and found them to far for the door to close. Removed the screws then pushed the steps against the body. Put the screws in place and checked the entry door to verify it closed properly. Added the other screws. No other adjustments required.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	34.00
<b>Subtotal for Job #1:</b>			<b>34.00</b>

#### Job #2 - Warranty

COMPLAINT: D SEALS ON INSIDE COMING OFF INSIDE  
ALONG TOP AND SIDES

CAUSE: Added screws at the end of d seals

CORRECTION: Inspected the d seals found them falling off the flap seal along the top and sides. Put the side seals back on then added screws at the top to hold them in place. Pulled off the top seal then slid it back onto the flap seal and put a screw on each end. Ran the slideroom in and out 4 times to verify the slideroom was not knocking of the d seal.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	51.00
<b>Subtotal for Job #2:</b>			<b>51.00</b>

Parts Total:	0.00
Labour Total:	85.00
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>85.00</b>

Customer #: 54995  
HENDERSON, PERRY

