



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74286
Promised Date: 24 JUL 24



CUSTOMER WORK ORDER

WO #: 74286 (Appointment Date: 22 JUL 2024 - Time: 10:00am)
Customer: 54284 - BERRYHILL,
PATRICK - 210-897-2126
Tag:
Author: BJW
Location: 0730 CHECK PREAUTH

Stock #:
Stock Desc: 2022 5W ALLIANCE
PARADIGM
Chassis #:
Serial #: 7M5FP4225NB200813
Mileage:
Licence:

Invoice #:
Date In: 22 JUL 24
Promised: 31 JUL 24
Date Sched:
Completed: 30 JUL 24
Warr. Date:

Job #1 - External

Transferred to BAS*74317 on 24 JUL 24
Estimate amount was 0.00
AWNING HAS A RIP IN IT, TRY FOR WARRANTY PER PARADIGM REP. FABRIC IS IN CASHIER
OFFICE
CUSTOMER HAS ITEMS IN REFRIGERATOR. PLEASE KEEP UNIT PLUGGED IN AS MUCH AS
POSSIBLE.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Subtotal for Job #1:			0.00

Job #2 - External

COMPLAINT: Transferred to BAS*74317 on 24 JUL 24
Estimate amount was 0.00
WATER HEATER OR WATER PUMP IS LEAKING. HE IS NOTICING WATER IN THE AREA

CAUSE: Pulled unit up to shop. Hooked up shore power and city water. Pressurized water system and turned on water heater. Removed panel that leads behind water pump and water heater. The pump is not leaking. Checked lines and fittings around the back of the water heater. After inspection, I noticed water has leaking all the way down the wall and is collecting on the ground outside. Went inside and found an access panel for the shower faucet. Removed panel. The hot water line is leaking at the shut-off valve. Had to cut the wall panel to get to the valve and clamp rings. Removed clamp rings and valve. Installed new valve and crimp rings. Installed cone washer. Secured water line. Pressurized water system to test for leaks. No leaks present. I'm going to leave the unit under pressure to see if everything else is good. No leaks present. Placed wall panels. Cleaned up mess.

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #2:				0.00

Customer #: 54284
BERRYHILL, PATRICK





Job #3 - External

COMPLAINT: Transferred to BAS*74317 on 24 JUL 24

Estimate amount was 0.00

DRAWERS IN MAIN CHEST IN BEDROOM IN FRONT OF BED NEED GUIDES REALIGNED

CAUSE: RESET DRAWER TRACKS. APPLIED LUBRICANT. DRAWER SHUTS AS IT SHOULD.

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Subtotal for Job #3:			0.00

Job #4 - Warranty

COMPLAINT: 22-270 LP QUICK CONNECT RECALL

CAUSE: Removed l.p. Quick connect. Took over to vice and removed adapter. Installed new quick connect and adapter to manifold with pipe sealer.

CORRECTION: .

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	136.00
Subtotal for Job #4:			136.00

Job #5 - Warranty

COMPLAINT: TSB 3 23-701 RECALL SOLAR INLET

CAUSE: Removed solar inlet. Hole isn't large enough to pull wires through. Took a multitool and cut hole. Pulled wires. Removed wire caps. Installed butt connectors. Applied electrical tape. Secured inlet to roof. Sealed with dicor.

CORRECTION: .

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		ZMS	85.00
Parts				
Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	7.99	7.99
Subtotal for Job #5:				92.99

Job #6 - External

Transferred to BAS*74317 on 24 JUL 24

Estimate amount was 0.00

HAS A GOOD SAM CONTRACT

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Subtotal for Job #6:			0.00

Job #7 - External

Transferred to BAS*74317 on 24 JUL 24

Estimate amount was 0.00

CUSTOMER IS LIVING IN UNIT AND NEEDS A QUICK TURN AROUND



W/O: 74286
Promised Date: 31 JUL 24



Customer #: 54284
BERRYHILL, PATRICK



Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #7: 0.00

Job #8 - External

Transferred to BAS*74317 on 24 JUL 24

Estimate amount was 0.00

CUSTOMER ADVISES THAT THE OFF DOOR REAR SLIDE HAS A SEAL STRIP THAT YOU CAN SEE IS PULLING AWAY FROM THE SLIDE ROOM WHEN YOU ARE ON TOP OF THE UNIT.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #8: 0.00

Job #9 - External

COMPLAINT: Transferred to BAS*74317 on 24 JUL 24

Estimate amount was 0.00

THERE IS WATER DRIPPING DOWN THE WATER LINES OF THE FAUCET WHEN YOU LOOK UP AT THE FAUCET FROM UNDER THE SINK.

CAUSE: KITCHEN faucet is leaking internally. Need to replace. See pics.

CORRECTION: .

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #9: 0.00

Parts Total: 7.99
Labour Total: 221.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 228.99

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 Jul 2024

