

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1996341
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FELB1SW029877
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	320 / 320
OWNER INFORMATION		ITEM #	FET22MLS-320
		DEALER RO #	74291
		CLAIM START DATE	07/24/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase	WARRANTY EXPIRATION DATE
-------------------------	--------------------------

Claim Line Details

Labor					
Line# 1	Operation Code	Operational Description			
	30-104-01-00-001207	Valance - Interior/Cushions-Dinette-Mattress-Curtains/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2024-07-24 11:26:26 :: THE VALANCE OVER THE EMERGENCY WINDOW IS NOT MOUNTED THE VALANCE OVER THE EMERGENCY WINDOW IS NOT MOUNTED Removed rollup shade that is mounted crooked and remounted straight. Mounted valance over blind.				
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$85.00	
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$68.00	
	Notes				
	R&RI shade to straighten repair code 30-99-01-00-001021 = 0.20; mount valance repair code 30-99-01-00-001030 = 0.20				
Labor					
Line# 2	Operation Code	Operational Description			
	60-136-15-00-001499	Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2024-07-24 11:27:16 :: THE HOT WATER LINE UNDER THE KITCHEN SINK LEAKS HOT WATER LINE UNDER KITCHEN SINK LEAKS Removed silverware drawer and panels for access to fitting that leaks. Disconnected hot water line from faucet water line. Fitting did not have a cone washer in connection. Installed cone washer and reconnected fitting. Turned on water and checked fitting for leak. No leak found at this time. Reinstalled silverware drawer and access panels below sink.				
Model#	Dlr Sub Hrs	0.70	Sub Labor Amt	\$119.00	
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$68.00	
	Notes				
	R&RI drawer and panels = 0.20; loosen fitting and install cone washer seal and tighten fitting = 0.20				
Labor					
Line# 3	Operation Code	Operational Description			
	60-138-24-00-001535	Drainage Lines - Plumbing/Drainage System/Repair/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : bhoffman@americanrvcenter.com, 2024-07-24 11:27:57 :: THE KITCHEN SINK DRAIN LEAKS THE KITCHEN SINK DRAIN LEAKS Removed silver ware drawer for access to drain. Water is leaking at a glued fitting. Cut fitting off. Fitting was not glued around the whole diameter, allowing water to leak at the fitting. Cut bad fitting off. Installed a new fitting and reassembled drain pipes. Checked fitting for leaks. No leaks at this time.				
Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$170.00	
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$68.00	
	Notes				
	drawer was already removed for repair line 2; cut off drain fitting and replace = 0.40				

Submitted	Labor Amt	\$374.00	Approved	Labor Amt	\$204.00
-----------	-----------	----------	----------	-----------	----------

Parts & Freight	\$0.00
Total	\$374.00

Parts & Freight	\$0.00
Total	\$204.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.