

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1997690
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAEC9RK006310
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	203 / 203
OWNER INFORMATION		ITEM #	BCAT164BHX
ANGELA K GRAY		DEALER RO #	74294
1203 GRAND AVE		CLAIM START DATE	07/25/2024
Washington, IN 47501		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	08/14/2023	WARRANTY EXPIRATION DATE	08/14/2024

Claim Line Details

Labor				
Line# 1	Operation Code	Operational Description		
	70-671-01-00-001464	Inside Shroud - Appliances/Roof AC (GE)/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-07-25 09:39:01 :: a/c is leaking from the switch inside while not raining Divider was not set in proper Plugged in the shore power cord then turned the ac on max. After letting the camper set for 2 days found water dripping from the ac knobs. Took pictures of the ac. Unscrewed the ceiling cover and inspected. Found the divider not setting as it should, it was leaning to the exhaust side. Moved the divider in place then used foil tape to help hold in place. Put the ceiling cover back up and screwed in place. Ran the ac longer but never found any more leaks.			
	Model# NA	Dlr Sub Hrs	0.35	Sub Labor Amt \$59.50
	Serial# NA	Appr Hrs	0.35	Appr Labor Amt \$59.50
	Notes			
	AUTHORIZED AS REQUESTED			
Labor				
Line# 2	Operation Code	Operational Description		
	70-148-01-11-004154	JBL Radio - Appliances/Radio/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-07-25 09:42:24 :: the speaker on the outside is not working right A - left or right no sound Pushed the power button on the radio, speaker A which is outside has no sound. Switched over to speaker B and has sound. Had both A and B on, still no A speaker. Unscrewed the outside speaker A then checked it's connection. Radio is tied into A left speaker, switched to A right speaker connection and still no sound. Connected the B left to the outside speaker and now the outside speaker has sound. The A side quit working. Put in po sheet for a new radio.			
	Model# JBL-AURA-CUBE	Dlr Sub Hrs	0.50	Sub Labor Amt \$85.00
	Serial# 2208000002651	Appr Hrs	0.50	Appr Labor Amt \$85.00
	Notes			
	AUTHORIZED AS REQUESTED			

Submitted	Labor Amt	\$144.50	Approved	Labor Amt	\$144.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$144.50		Total	\$144.50

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.

