



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74294
Promised Date:



Customer #: 53904
GRAY, ANGELA K.



CUSTOMER WORK ORDER

WO #: 74294 (Appointment Date: 23 JUL 2024 - Time: 09:30am)

Customer: 53904 - GRAY, ANGELA K. -
812-698-9545

Tag: BJ - RADIO ORDERED. 7-25-24

Author: BJW

Location: 0801 CHECK PARTS

Stock #: 11129

Stock Desc: 2024 TT COACHMEN

CATALINA SUMMIT SERIES 164BHX

Chassis #: 5ZT2CAEC9RK006310

Serial #: 5ZT2CAEC9RK006310

Mileage: 0

Licence:

Invoice #:

Date In: 23 JUL 24

Promised: 31 JUL 24

Date Sched:

Completed: 30 JUL 24

Warr. Date: 14 AUG 23

Job #1 - Warranty

COMPLAINT: a/c is leaking from the switch inside while not raining

CAUSE: Divider was not set in proper

CORRECTION: Had to pull the key cylinder to find the key number to unlock the deadbolt. Plugged in the shore power cord then turned the ac on max. After letting the camper set for 2 days found water dripping from the ac knobs. Took pictures of the ac. Unscrewed the ceiling cover and inspected. Found the divider not setting as it should, it was leaning to the exhaust side. Moved the divider in place then used foil tape to help hold in place. Put the ceiling cover back up and screwed in place. Ran the ac longer but never found any more leaks.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	59.50
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 59.50

Job #2 - Warranty

COMPLAINT: the speaker on the outside is not working right

CAUSE: A - left or right no sound
Radio

CORRECTION: Pushed the power button on the radio, speaker A which is outside has no sound. Switched over to speaker B and has sound. Had both A and B on, still no A speaker. Unscrewed the outside speaker A then checked it's connection. Radio is tied into A left speaker, switched to A right speaker connection and still no sound. Connected the B left to the outside speaker and now the outside speaker has sound. The A side quit working. Put in po sheet for a new radio. Removed radio and installed new one. Tested

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	85.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
F100323657	CUBE, JBL AURE HIGH PERFORMANCE MECH	1.00	112.25	112.25



Other Services

Code	Description	Qty	Price	Total
FRT	UPS-STEREO	1.00	18.24	18.24

Subtotal for Job #2: 215.49

Parts Total: 112.25
Labour Total: 144.50
Sublet Total: 0.00
Extras Total: 18.24

WORK ORDER TOTAL: 274.99

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 Jul 2024

W/O: 74294
Promised Date: 31 JUL 24



Customer #: 53904
GRAY, ANGELA K.

