



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74341
Promised Date:
24 JUL 24

CUSTOMER WORK ORDER

WO #: 74341 (Appointment Date: 27 JUL 2024 - Time: 09:30am)

Customer: 46823 - BAUMBERGER,
CRYSTAL K. - (812) 480-4063

Tag:
Author: BJW

Location: 0810 CHECK PREAUTH

Stock #:
Stock Desc: 2022 TT FOREST RIVER
CATALINA 30THT
Chassis #:
Serial #: 5ZT2CAVB8PX027236
Mileage:
Licence:

Invoice #:
Date In: 27 JUL 24
Promised: 31 JUL 24
Date Sched:
Completed: 31 JUL 24
Warr. Date:

Job #1 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THERE IS WATER RUNNING IN AROUND THE GARAGE DOOR FOR THE TOY HAULER. CUSTOMER ADVISES THAT THE WATER COMES IN FROM THE TOP AND RUNS DOWN TO THE FLOOR

CAUSE: Garage door

CORRECTION: Found a few spots above door. Took pics. Taped off and put black silicone on. Let dry and water tested. No leaks

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	51.00

Parts

Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	18.41	18.41

Subtotal for Job #1: 69.41

Job #2 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE SHOWER IS LEAKING INTO THE CABINET BEHIND IT. THIS IS IN THE VERY BACK CORNER OF THE SHOWER. CUSTOMER ADVISES THAT THE WATER MAKES IT'S WAY TO THE LIVING ROOM.

CAUSE: Shower

CORRECTION: Inspected shower and found they only siliconed to the cabinet on the outside of the bottom track. Siliconed the inside and let dry. Than water tested. No leaks.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	51.00
Z990	MISCELLANEOUS REPAIR	BB	0.00

Subtotal for Job #2: 51.00

Job #3 - Warranty

COMPLAINT: THE SEAL ON THE OFF DOOR SLIDE FRONT CORNER IS PULLING OFF WHEN THE ROOM RUNS IN AND OUT.

CAUSE: Seal



Customer #: 46823
BAUMBERGER, CRYSTAL
K.



CORRECTION: Removed bulb seal and put it back on right.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	13.60
Z990	MISCELLANEOUS REPAIR	BB	11.90

Subtotal for Job #3: 25.50

Job #4 - Warranty

COMPLAINT: THERE IS A HOLE IN THE SEAL OF THE KITCHEN SLIDE. THIS IS MOST NOTICED WHEN INSIDE THE TRAILER AND LOOKING INTO THE REAR CORNER OF THE SLIDE ROOM.

CAUSE: Bulb

CORRECTION: Removed damaged bulb seal. Installed new seal.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	22.10
Z990	MISCELLANEOUS REPAIR	BB	3.40

Parts

Part #	Description	Qty	Price	Total
338809	Seal - D Seal - EK - Modified	6.00	0.97	5.82

Subtotal for Job #4: 31.32

Job #5 - Warranty

COMPLAINT: THE CAULKING ON THE OUTSIDE OF THE SLIDE ROOM (FRONT SIDE OF OFF DOOR SLIDE ROOM) IS PULLING APART.

CAUSE: Caulking

CORRECTION: Taped off and put new caulking on.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	34.00

Parts

Part #	Description	Qty	Price	Total
F100359506	SILICONE, NEUTRAL CURE SILICONE 10.3	1.00	12.09	12.09

Subtotal for Job #5: 46.09

Job #6 - Warranty

COMPLAINT: ONE OF THE RED MARKER LAMPS ON THE DOOR SIDE REAR IS CRACKED.

CAUSE: Light

CORRECTION: Put new lense on.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	34.00

Parts

Part #	Description	Qty	Price	Total
210628	MCL0032RBS 1-LED RED MARKER LIGHT	1.00	3.88	3.88

Subtotal for Job #6: 37.88

Job #7 - Warranty

COMPLAINT: THERE IS A ELASTIC RUBBER STRAP ON THE OFF DOOR SIDE OF THE RAMP. THIS

W/O: 74341
Promised Date: 31 JUL 24



Customer #: 46823
BAUMBERGER, CRYSTAL
K.



IS ON THE HARDWARE FOR THE PATIO. SEE BJ FOR DETAILS.

CAUSE: Strap

CORRECTION: Ordered new strap on 7/29/24. Drilled out rivet and installed new strap.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	51.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00

Parts

Part #	Description	Qty	Price	Total
F100361420	BUNGEE STRAP W/ HOOK AND EYELET 4-7/	1.00	17.76	17.76

Other Services

Code	Description	Qty	Price	Total
FRT	UPS- STRAP	1.00	18.24	18.24

Subtotal for Job #7: 87.00

Job #8 - Warranty

COMPLAINT: PANELING LOOSE ABOVE GARAGE DOOR

CAUSE: Wall

CORRECTION: Removed rubber ceiling trim. Stapled back wall board. Installed new baton strip.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	102.00
Z990	MISCELLANEOUS REPAIR	BB	0.00

Subtotal for Job #8: 102.00

Parts Total: 57.96
 Labour Total: 374.00
 Sublet Total: 0.00
 Extras Total: 18.24
WORK ORDER TOTAL: 450.20

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Aug 2024

W/O: 74341
Promised Date: 31 JUL 24



Customer #: 46823
K. BAUMBERGER, CRYSTAL

