

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2006555
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARB4RU043934
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT261BHS-8
JAY P STEVENS		DEALER RO #	74351
1076 E 350 S		CLAIM START DATE	08/01/2024
Princeton, IN 47670		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	07/31/2024	WARRANTY EXPIRATION DATE	07/31/2025

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	70-671-01-11-003983	Wall Thermostat - Appliances/Roof AC (GE)/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-08-01 11:57:02 :: A/C THERMOSTAT IS BROKEN CHECK AND ADVISE thermostat housing broke had to rob from unit on lot to get customer going on delivery, filled out sheet to get new one to replace on lot.			
	Model# RARWT2B6	Dlr Sub Hrs	0.50	Sub Labor Amt \$85.00
	Serial# 803300290147	Appr Hrs	0.50	Appr Labor Amt \$85.00
	Notes			
	AUTHORIZED AS REQUESTED			

Labor

Line# 2	Operation Code	Operational Description		
	30-101-02-00-001076	Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-08-01 12:07:50 :: BATHROOM DOOR WILL NOT STAY SHUT Trim and shim Removed the latch plate then put in shims behind the plastic door frame. Moved the latch plate up and out then trimmed the hole to clear the latch. Now door stays shut.			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$34.00
	Notes			

Submitted	Labor Amt	\$119.00	Approved	Labor Amt	\$119.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$119.00		Total	\$119.00

DEALER _____ DATE _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE

All repairs described have been inspected and are satisfactory.