

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2009565
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CANB1RU042729
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT243RBSLE
DONALD H BRADLEY JR.		DEALER RO #	74390
949 OSAGE DR		CLAIM START DATE	08/05/2024
Henderson, KY 42420		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	04/15/2024	WARRANTY EXPIRATION DATE	04/15/2025

Claim Line Details

Labor				
Line# 1	Operation Code	Operational Description		
	60-141-19-00-001611	Glass Shower Enclosure - Plumbing/Shower, Tub Surround/Reseal/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-08-05 11:49:35 :: CUSTOMER ADVISES THAT THERE IS WATER RUNNING OUT FROM UNDER THE SHOWER INTO THE FLOOR WHEN IN USE. CUSTOMER IS UNSURE WHERE THE LEAK IS AT. WHEN LOOKING AT THE SHOWER, THE LEAK IS COMING FROM THE LEFT SIDE. SEE BJ FOR EXACTE LOCATION Shower The two side glass panels leak over track when spraying water on them. Siliconed the edges and the glass on both sides. Put a shim under pan. Let dry and water test.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00
Notes				

Submitted	Labor Amt	\$34.00	Approved	Labor Amt	\$34.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$34.00		Total	\$34.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	