

Pre-Authorization

Pre-Authorization number PA03715587 Reference no: 74403 Status: Approved Approved by papca Approved date 8/6/2024
Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDFCGM26R2500457 3/22/2024
600 E Baseline Rd
Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	1101903B	Leaf Spring - DS I	0.00	0.50	0.50		1	0.50	Complaint: CUSTOMER ADVISES THAT WHEN HE LOOKS IN HIS REAR VIEW MIRROR, IT APPEARS THAT THE CAMPER IS LEANING TO ONE SIDE. Cause: FOUND THE LEFT SPRING HAS COLLAPSED Correction: NEED TO REMOVE AND REPLACE LEFT SPRING KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB: Vendor Charge Back item.

Pre-Authorization number PA03715587

0.50

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company