

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 74405
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 10245 - CHAD T. PRICE
Address: 1118 DORAL ST MT CARMEL, IL

62863

Phone: 618-263-7854

Stock Number: 10871 - 2023 CATALINA 313RLTSLE 5ZT2CAWB2PX028798

VIN: 5ZT2CAWB2PX028798 HIN: SER#: 5ZT2CAWB2PX028798

Mileage: 0 Work Order Comp: 26 AUG 24

Auth. No: Dealer #:

Warr. Date: 30 MAY 23 Work Order Date: 02 AUG 24 Inv #: 408644

WO # Job # Description JOB INFORMATION

74405	2	seal tape on all 3 slides see Chad Slideroom roof Cleaned off all three slideroom roofs on taped area. Put new extream tape on. Siliconed against t bar. Put black extream tape on corners of t bar over the screws. Put vinyl insert in gutter on small awning. Siliconed. Took pics.
74405	7	All the slide corner caps have made a hole in the bulb seals Bulb seal Put black extream tape on corners of t bar to cover screw heads. Replaced bulb seals per Chad. Sprayed seal saver on all seals.
74405	4	Replace gutter over the door side slide room it puddles up and leaked over slide room install new gutter over entire side Gutters Tie back awning arms. Removed both gutters on door side. Installed new gutters. Started from the center of the coach and dropped to the down spots. Siliconed under the gutters. Dicor on top of gutters. Put vinyl insert in on both sides of the gutters.
74405	5	Door side slide trim coming loose on the rear top toward the camper Trim Removed screws and put in longer screws.
74405	6	Slide ski is loose on the door side slide just rear and the front

Claim : 74405

 WO # Job # Description JOB INFORMATION

off door side front slide room

Ski

Put tape primer on floor. Put new tape on and stick back.

74405 10 PULL THE WALL BOARD LOOSE ON THE DOOR SIDE SLIDE ROOM TO MAKE
 SURE THERE IS NO ISSUES WITH WATER NEAR THE DINNETT
 Water leak
 Removed awning arms. Removed t bars. Removed j wrap. Remove three
 pieces of siding and check insulation. Take pics. Some insulation
 was wet. Removed and put fan on walls. They were not wet but put
 fan on anyway. I fixed the problem by putting vinyl insert on
 gutter rail.and siliconed where needed. Remove silicone on
 siding.Put new insulation in. Put siding back up. Put t bars
 back. Tape off and siliconed. Put awning rails back. Siliconed
 all screw holes first. Moved rear arm down 1 inch.

 Part No Job# Description PARTS Qty Price Total

 500629 2 SIKASIL N PLUS WHITE 2.00 18.22 36.44
 420104 2 QUICK ROOF EXTREME 4" X 25' 3.00 33.12 99.36
 420111 2 QUICK ROOF EXTREME - BLACK FOR RV 1.00 33.12 33.12
 338809 7 Seal - D Seal - EK - Modified 30.00 0.97 29.10
 20-6957 4 INSERT GUTTER/AWNING RAIL- BLACK- 2.00 66.87 133.74
 500447 4 E469 BLACK HD 1" x 100' INSERT TR 1.00 20.33 20.33
 410062 4 NON SELF LEVELING DICOR 1.00 7.31 7.31
 500627 4 CLEAR SIKASIL PLUS 2.00 18.41 36.82
 F100134895 10 12" SILVER METAL X 167" 1.00 32.32 32.32
 F100163427 10 METAL, .024 12 X 210" SM 1" CM RE 1.00 40.49 40.49
 F100359506 10 SILICONE, NEUTRAL CURE SILICONE 1 2.00 12.09 24.18

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.02 170.00 3.40
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.50 170.00 85.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 2.48 170.00 421.60
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.70 170.00 119.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 1.20 170.00 204.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.10 170.00 17.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 1.00 170.00 170.00
 Z990 10 MISC LABOUR CODE (EXTERNAL) 2.50 170.00 425.00
 Z990 10 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 10 MISC LABOUR CODE (EXTERNAL) 2.50 170.00 425.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 10 FREIGHT & CRATE - METAL 1.00 572.55 572.55

Claim : 74405

Excode Job# Description EXTRAS Qty Price Total

Parts Total: 493.21
Labour Total: 1,870.00
Sublet Total: 0.00
Extras Total: 572.55

>>>> Claim Total: 2,935.76

Customer Signature: _____

Date: _____