



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74405
Promised Date:
24 AUG 24

CUSTOMER WORK ORDER

WO #: 74405 (Appointment Date: 02 AUG 2024 - Time: 11:00am)

Customer: 10245 - PRICE, CHAD T. -
618-263-7854

Tag:

Author: BH

Location: 0826 BH TO CLOSE

Stock #: 10871

Stock Desc: 2023 TT COACHMEN

CATALINA 313RLTSLE

Chassis #: 5ZT2CAWB2PX028798

Serial #: 5ZT2CAWB2PX028798

Mileage: 0

Licence:

Invoice #:

Date In: 02 AUG 24

Promised: 31 AUG 24

Date Sched:

Completed: 26 AUG 24

Warr. Date: 30 MAY 23

Job #1 - Internal

COMPLAINT: CUSTOMER ADVISES THAT THERE IS QUITE A
BIT OF WATER IN THE FLOOR OF THE UNIT
AND YOU CAN SEE WHERE WATER IS SOKING
THROUGHT THE UNDERSIDE OF THE SLIDE
ROOM. WE HAVE HISTORY ON THIS

CAUSE: Slideroom

CORRECTION: After me and Chad went over everything. He said looks good. Done

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: seal tape on all 3 slides see Chad

CAUSE: Slideroom roof

CORRECTION: Cleaned off all three slideroom roofs on taped area. Put new extream tape on. Siliconed
against t bar. Put black extream tape on corners of t bar over the screws. Put vinyl insert in gutter on small
awning. Siliconed. Took pics.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	3.40
Z990	MISC LABOUR CODE (EXTERNAL)	BB	85.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	421.60

Parts

Part #	Description	Qty	Price	Total
500629	SIKASIL N PLUS WHITE	2.00	18.22	36.44
13-1413	QUICK ROOF EXTREME 4" X 25'	3.00	33.12	99.36
4351	QUICK ROOF EXTREME - BLACK FOR RV'S	1.00	33.12	33.12



Customer #: 10245
PRICE, CHAD T.





Subtotal for Job #2: 678.92

Job #3 - Internal

COMPLAINT: Dinette window leaking from the top on the inside and leaking on the table

CAUSE: Window

CORRECTION: Sprayed water for two hours . No leak.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: Replace gutter over the door side slide room it puddles up and leaked over slide room install new gutter over entire side

CAUSE: Gutters

CORRECTION: Tie back awning arms.Removed both gutters on door side. Installed new gutters. Started from the center of the coach and dropped to the down spots. Siliconed under the gutters. Dicor on top of gutters. Put vinyl insert in on both sides of the gutters.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	204.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00

Parts

Part #	Description	Qty	Price	Total
20-6957	INSERT GUTTER/AWNING RAIL-BLACK- 16	2.00	66.87	133.74
E469	E469 BLACK HD 1" x 100' INSERT TRIM	1.00	20.33	20.33
13-1287	NON SELF LEVELING DICOR	1.00	7.31	7.31
500627	CLEAR SIKASIL PLUS	2.00	18.41	36.82

Subtotal for Job #4: 402.20

Job #5 - Warranty

COMPLAINT: Door side slide trim coming loose on the rear top toward the camper

CAUSE: Trim

CORRECTION: Removed screws and put in longer screws.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	17.00

Subtotal for Job #5: 17.00

Job #6 - Warranty

COMPLAINT: Slide ski is loose on the door side slide just rear and the front off door side front slide room

CAUSE: Ski

CORRECTION: Put tape primer on floor. Put new tape on and stick back.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Z990 MISC LABOUR CODE (EXTERNAL) BB 170.00

Subtotal for Job #6: 170.00

Job #7 - Warranty

COMPLAINT: All the slide corner caps have made a hole in the bulb seals

CAUSE: Bulb seal

CORRECTION: Put black extream tape on corners of t bar to cover screw heads. Replaced bulb seals per Chad. Sprayed seal saver on all seals.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	119.00

Parts Part #	Description	Qty	Price	Total
338809	Seal - D Seal - EK - Modified	30.00	0.97	29.10

Subtotal for Job #7: 148.10

Job #8 - Internal

COMPLAINT: Check the kitchen window to make sure it does not leak

CAUSE: Window

CORRECTION: Ran water on window for two hours. No leaks

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Subtotal for Job #8: 0.00

Job #9 - Internal

COMPLAINT: Check awning on the rear the rear arm see if it can be moved down any with out making new holes

CAUSE: Arm

CORRECTION: Moved rear awning arm down 1 inch. Silicone all screw holes

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: PULL THE WALL BOARD LOOSE ON THE DOOR
SIDE SLIDE ROOM TO MAKE SURE THERE IS NO
ISSUES WITH WATER NEAR THE DINNETT

CAUSE: Water leak

CORRECTION: Removed awning arms. Removed t bars. Removed j wrap. Remove three pieces of siding and check insulation. Take pics. Some insulation was wet. Removed and put fan on walls. They were not wet but put fan on anyway. I fixed the problem by putting vinyl insert on gutter rail.and siliconed where needed. Remove silicone on siding.Put new insulation in. Put siding back up. Put t bars back. Tape off and siliconed. Put awning rails back. Siliconed all screw holes first. Moved rear arm down 1 inch.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	425.00

W/O: 74405
Promised Date: 31 AUG 24



Customer #: 10245
PRICE, CHAD T.



W/O: 74405
Promised Date: 31 AUG 24



Customer #: 10245
PRICE, CHAD T.



Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	425.00

Parts

Part #	Description	Qty	Price	Total
F100134895	12" SILVER METAL X 167"	1.00	32.32	32.32
F100163427	METAL, .024 12 X 210" SM 1" CM REG3	1.00	40.49	40.49
F100359506	SILICONE, NEUTRAL CURE SILICONE 10.3	2.00	12.09	24.18

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT & CRATE - METAL	1.00	572.55	572.55

Subtotal for Job #10: 1,519.54

Parts Total: 493.21
Labour Total: 1,870.00
Sublet Total: 0.00
Extras Total: 572.55
WORK ORDER TOTAL: 2,935.76

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 29 Aug 2024

