



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74435
Promised Date:
24 AUG 24



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 74435

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag: PH - ORDER PARTS. 8-7-24
Author: PH
Location: 1202 BH TO CLOSE

Stock #: 11442
Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 231MKS
Chassis #: 5ZT2CAMB8SU044310
Serial #: 5ZT2CAMB8SU044310
Mileage:
Licence:

Invoice #:
Date In: 06 AUG 24
Promised: 31 AUG 24
Date Sched:
Completed: 30 NOV 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*74977 on 09 OCT 24
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT PDI - NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Filled LP tanks. Installed new battery box. Battery cables too long. Cut cables off to fit. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Removed spare tire from mounting under unit and turned over so that tire pressure can be checked without dropping down. Checked roof. Checked power cord. Checked all interior lights. Checked converter output. Checked power awning. Checked entrance door and all compartment doors. Checked entrance door foldup steps. Removed packing and shipping tape from all appliances. Checked all windows and blinds. Checked all cabinets and drawers. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Filled fresh water tank and flushed antifreeze from water pump. Connected to city water and flushed antifreeze from all water lines and faucets. Checked all water lines and faucets for leaks. Opened by-pass on water heater and filled. Purged all air from water system. Operated all colors of awning lights. Took pictures and recorded all serial numbers. Performed LP drop test and set LP pressure at 10in.wc. Filled all holding tanks and checked monitor panel. Operated all appliances including water heater on both LP and electric. Operated Air Conditioner and Furnace. Operated Refrigerator on 12 volts. Drained all holding tanks. Moved unit back to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: THE ENTRY DOOR STEPS ARE HITTING THE DINNETTE SEAT WHEN THEY ARE FOLDED UP.



NOTED ON DELIVERY

CAUSE: THE ENTRY DOOR STEPS ARE HITTING THE DINNETTE SEAT WHEN THEY ARE FOLDED UP

CORRECTION: Removed mounting screws and moved steps over to clear dinnette seat back when foled up. Replaced all mounting screws to secure steps in position. Checked operation of steps folding out and back in. steps now have clearance and do not hit dinnette seat back.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	17.00

Parts				
Part #	Description	Qty	Price	Total
F100359506	SILICONE, NEUTRAL CURE SILICONE 10.3 OZ ALUMINUM SIL-7500SILFLEX	1.00	12.09	12.09

Subtotal for Job #1: 29.09

Job #2 - Warranty

COMPLAINT: THE SHOWER SURROUND IS BOWED OUT ON THE EDGES.
NOTED ON DELIVERY

CAUSE: THE SHOWER SURROUND IS BOWED OUT ON THE EDGES (NOTED ON DELIVERY)

CORRECTION: Added extra screws along edges to hold shower surround flat against walls.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	34.00

Subtotal for Job #2: 34.00

Job #3 - Warranty

COMPLAINT: SCREW POKING METAL BY EXCAPE WINDOW.
NOTED ON DEL

CAUSE: SCREW POKING METAL BY ESCAPE WINDOW

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	680.00

Parts				
Part #	Description	Qty	Price	Total
F100418575	GRAPHIC, #8 ODS CATALINA SUMMIT 2024	1.00	1.16	1.16
F100418567	GRAPHIC, #6 ODS CATALINA SUMMIT 2024	1.00	3.88	3.88
F100134895	12" SILVER METAL X 167"	1.00	32.32	32.32

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-DECALS	1.00	18.24	18.24
FRT	FREIGHT-METAL	1.00	523.78	523.78

Subtotal for Job #3: 1,259.38

Job #4 - Warranty

COMPLAINT: TEST TV NOT PICKING UP CHANNELS

CAUSE: TEST TV NOT PICKING UP CHANNELS

CORRECTION: Checked all cable connections on back of booster. Found Cable from antenna was



connected to bedroom TV outlet. Switched connections. Ran channel again. This time test TV picks up channels at all three locations.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	34.00

Subtotal for Job #4: 34.00

Parts Total: 49.45

Labour Total: 765.00

Sublet Total: 0.00

Extras Total: 542.02

WORK ORDER TOTAL: 1,356.47

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 04 Dec 2024

W/O: 74435
Promised Date: 31 AUG 24



Customer #: 1000
BASDEN'S AMERICAN RV,

