



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74445
Promised Date:
24 AUG 24

CUSTOMER WORK ORDER

WO #: 74445

Customer: 54758 - HALL, MICHAEL S. -
812-827-1240
Tag: BH - PARTS ORDERED. 9-16-24
Author: BH
Location: 1005 CHECK PREAUTH

Stock #: 11377
Stock Desc: 2024 TT KEYSTONE
SPRINGDALE 260BHC
Chassis #: 4YDTSGL23R7104318
Serial #: 4YDTSGL23R7104318
Mileage:
Licence:

Invoice #:
Date In: 06 AUG 24
Promised: 31 AUG 24
Date Sched:
Completed: 30 SEP 24
Warr. Date: 18 MAY 24

Job #1 - Warranty

COMPLAINT: AC FROZE UP PAST 2 TIMES THEY WENT CAMPING.

CAUSE: Pulled unit outside of bay. Hooked up to shore power and turned on ac. Letting run overnight. Air conditioner will freeze up when the thermostat is maxed out. Tech suggests replacing the thermostat. Any other suggestions from warrty or furrion would help. REMOVED UPPER CEILING ASSEMBLY AND REPLACED WITH A DIFFERENT FURRIOR STYLE ASSEMBLY. THRMOSTATS WAS ALSO REPLACED. LETTING RUN TO SEE IF UNIT FREEZES UP AGAIN. A/C FROZE UP WITH A DIFFERENT T STAT. REMOVED ADB AND LET RUN. AFTER TESTING WARRANTY APPROVED A NEW A/C/ UNIT. RECIEVED NEW A/C UNIT. REMOVED MOUNTING AHARDWARE. GOT A FORK TRUCK AND REMOVED A/C. PLACED NEW A/C ON ROOF AND POSITIONED OVER CUT OUT. INSTALLED HARDWARE AND PLENUM. LET UNIT RUN OVERNIGHT TO SEE IF IT FREEZES UP. CHECKED UNIT NEXT MORNING. A/C IS RUNNING NORMALLY WITHOUT FREEZING UP. PARKED UNIT.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	119.00
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	221.00

Parts

Part #	Description	Qty	Price	Total
2021123818	AIR DISTRIBUTION BOX W/MANUAL CONTROL, WHITE	1.00	111.21	111.21
698930	A/C - 15 BTU - Chill Air - High Effic	1.00	591.02	591.02

Other Services

Code	Description	Qty	Price	Total
FRT	CEVA FREIGHT - A/C	1.00	176.65	176.65

Subtotal for Job #1: 1,218.88

Job #2 - Warranty

COMPLAINT: RUBBER BOOT ON TOP TO RAISE JACK UO AND DOWN HAS A CUT IN RUBBER

CAUSE: PULLED UNIT INTO BAY. REMOVED COVER. THE SWITCH IS BUILT INTO THE JACK. THE ENTIRE JACK WILL NEED REPLACED. RECIEVED NEW JACK. REMOVED OLD JACK. INSTALLED



Customer #: 54758
HALL, MICHAEL S.

NEW JACK TO FRAME. SECURED IN LINE FUSE WITH HEAT SHRINK TERMINALS. HEATED
TERMINALS WITH HEAT GUN. ZIP TIED WIRES.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	85.00

Parts

Part #	Description	Qty	Price	Total
3291	3500# STROMBERG ELEC JACK -BULK	1.00	189.75	189.75

Subtotal for Job #2: 274.75

Job #3 - Warranty

COMPLAINT: OFF DOOR SIDE FRONT RUBBER DUST CAP CAME OFF

CAUSE: SECURED DUST CAP

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	34.00

Subtotal for Job #3: 34.00

Parts Total: 891.98
Labour Total: 459.00
Sublet Total: 0.00
Extras Total: 176.65
WORK ORDER TOTAL: 1,527.63

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited
to work performed. Consequential damages are not covered. All guaranteed work
must be completed in our service department.

Customer Signature : _____

Date: 30 Sep 2024

W/O: 74445
Promised Date: 31 AUG 24



Customer #: 54758
HALL, MICHAEL S.

