

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 74454
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11443 - 2025 CATALINA SUMMIT SERIES 261BH 5ZT2CARB5SU044287
VIN: 5ZT2CARB5SU044287 HIN: SER#: 5ZT2CARB5SU044287
Mileage: 0 Work Order Comp: 30 AUG 24
Auth. No: Dealer #:
Warr. Date: Work Order Date: 07 AUG 24 Inv #: 408865

WO #	Job #	Description	JOB INFORMATION

74454	1	BATTEN STRIP NEXT TO MAIN BED IS MISSING BATTEN STRIP NEXT TO MAIN BED IS MISSING A 24 in piece of trim is missing under cabinet over bed. 8-9-2024: Turned in parts request for new trim. 8/15/24: Received new batton strip. Moved unit into shop. Cut trim to fit and installed. Mocved unit back to sales lot.	
74454	2	BLIND OVER DINETTE WONT STAY UP BLIND OVER DINETTE WILL NOT STAY UP Checked operation of blind. Strings are loose. Tightened both strings. Now blind stays up.	
74454	3	CURBSIDE FRONT CLEARANCE LIGHT NOT WORKING CURBSIDE FRONT CLEARANCE LIGHT NOT WORKING Removed front clearance light. Removed light from front of unit. Pulled wires out of hole. Found bad crimps on both positive and negative wires to light. Cut off crimp connectors. Tested light at a battery. Light works ok. Reconnected all wires with new bell connectors. Checked operation of light. OK. Remounted light.	
74454	4	CURB SIDE REAR BRAKE NOT RELEASING CURBSIDE REAR BRAKE NOT RELEASING Jacked up unit and removed tire and wheel. Pryed drum loose and removed. Brake shoes are ok. Remounted drum and secured. Remounted tire and wheel. Tightened lug nuts and torqued to	

Claim : 74454

 WO # Job # Description JOB INFORMATION

specs. Adjusted all (4) brakes to be equal.

74454 5 FLAT TRIM COMING OFF UNDER BOTTOM BUNK BY WATER HEATER
 FLAT TRIM COMING OFF UNDER BOTTOM BUNK BY WATER HEATER
 Reattached flat trim under rear bottom bunk.

74454 6 TV WILL NOT PICK UP CHANNELS
 TV WILL NOT PICK UP CHANNELS.
 Removed Antenna booster from wall. Found antenna cable was
 connected to second TV. Second TV cable was connected to
 antenna. Switched cables to correct locations. Ran channel scan
 with cables connected to correct inputs on back of antenna
 booster. Antenna found 16 channels. Training is needed at
 factory on color of coax cables!!!!!!!

 Part No Job# Description PARTS Qty Price Total

 F100284346 1 BATTEN, #195 CHILI TEAK, 50G, 7/8 1.00 1.86 1.86

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.05 170.00 8.50
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.40 170.00 68.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.30 170.00 51.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 UPS-BATTEN 1.00 37.37 37.37

Parts Total: 1.86
 Labour Total: 229.50
 Sublet Total: 0.00
 Extras Total: 37.37

>>>> Claim Total: 268.73

Customer Signature: _____

Date: _____