

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2042521
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKC27SX164346
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT27LH
		DEALER RO #	74483
		CLAIM START DATE	08/30/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor

Line# 1

Operation Code	10-12-01-11-001293	Operational Description
		Slide Out Switch - Frame & Chassis/Slide Out System - Lippert/Replace/ Electrical
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2024-08-30 12:44:43 :: SLIDE ROOM NOT WORKING Slide room won't go out. Removed panel to check switch. Wire came off the back of the switch. Installed wire terminal to switch and slide room is working.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.30	\$51.00
Serial#	Appr Hrs	Appr Labor Amt
	0.30	\$51.00
Notes		

Labor

Line# 2

Operation Code	30-101-02-00-001077	Operational Description
		Hinged Passage Door Striker - Interior/Interior Doors/Adjust/No Tread Code
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2024-08-30 12:46:32 :: BEDROOM DOOR HITTING FRAME Painted 2 screws black. Secured screws to frame.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.10	\$17.00
Serial#	Appr Hrs	Appr Labor Amt
	0.10	\$17.00
Notes		

Labor

Line# 3

Operation Code	30-101-02-00-001077	Operational Description
		Hinged Passage Door Striker - Interior/Interior Doors/Adjust/No Tread Code
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2024-08-30 12:52:50 :: BATHROOM SHOWER NEEDS SECURED AND SEALED Secured panel with screw and sealed with silicone		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.10	\$17.00
Serial#	Appr Hrs	Appr Labor Amt
	0.10	\$17.00
Notes		

Labor

Line# 4

Operation Code	10-13-02-00-000211	Operational Description
		Slide Out Room - Frame & Chassis/Slide Out System/Adjust/No Tread Code
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2024-08-30 12:54:28 :: SLIDE ROOM WON'T OPEN ALL THE WAY THE BRACKETS TOWARDS THE REAR OF THE CAMPER DONT MATCH THE FRONT. THE SLIDE ROOM IS TIMING OUT BEFORE THE SLIDE CAN FULLY EXTEND. THIS IS ALSO CAUSING THE COUCH TO HIT THE SLIDE ROOM. COUCH WILL NOT EXTEND. NEED TO CONTACT WARRNTY FOR INSTRUCTIONS FOR REPAIR. Moved top		

