



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74483
Promised Date: 24 AUG 24

CUSTOMER WORK ORDER

WO #: 74483

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0905 CHECK PREAUTH

Stock #: 11445
Stock Desc: 2025 TT FOREST RIVER
CHEROKEE GREY WOLF 27LH
Chassis #: 4X4TCKC27SX164346
Serial #: 4X4TCKC27SX164346
Mileage: 0
Licence:

Invoice #:
Date In: 09 AUG 24
Promised: 31 AUG 24
Date Sched:
Completed: 31 AUG 24
Warr. Date:

Job #PDINTT - Internal

Transferred to BAS*74661 on 28 AUG 24
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: SLIDE ROOM NOT WORKING

CAUSE: Slide room won't go out. Removed panel to check switch. Wire came off the back of the switch. Installed wire terminal to switch and slide room is working.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	51.00

Subtotal for Job #1: 51.00

Job #2 - Warranty

COMPLAINT: BEDROOM DOOR HITTING FRAME

CAUSE: Painted 2 screws black. Secured screws to frame.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00

Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #2: 17.00

Job #3 - Warranty

COMPLAINT: BATHROOM SHOWER NEEDS SECURED AND SEALED

CAUSE: Secured panel with screw and sealed with silicone

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00

Subtotal for Job #3: 17.00

Job #4 - Warranty

COMPLAINT: SLIDE ROOM WON'T OPEN ALL THE WAY

CAUSE: THE BRACKETS TOWARDS THE REAR OF THE CAMPER DONT MATCH THE FRONT. THE SLIDE ROOM IS TIMING OUT BEFORE THE SLIDE CAN FULLY EXTEND. THIS IS ALSO CAUSING THE COUCH TO HIT THE SLIDE ROOM. COUCH WILL NOT EXTEND. NEED TO CONTACT WARRNTY FOR INSTRUCTIONS FOR REPAIR. Moved top and bottom brackets as close as I could to the facia board. Tightened cables. The slide room still won't open enough for the couch to open. Waiting on warranty to advise repair.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	85.00

Subtotal for Job #4: 85.00

Job #5 - Internal

COMPLAINT: THE ENTRY DOOR NEEDS TO BE ADJUSTED.

CAUSE: Pushed latch over with hammer. Door latches easily.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: THERE IS GLUE ON THE WATER HEATER DOOR.

CAUSE: Took a puttyknife and mineral spirits and scraped off the glue.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00

Subtotal for Job #6: 17.00

Job #7 - Warranty

COMPLAINT: THERE IS GLUE ON THE FLOOR IN THE KITCHEN

W/O: 74483
Promised Date: 31 AUG 24



Customer #: 1000
BASDEN'S AMERICAN RV,



CAUSE: Applied mineral spirits and removed glue with a shop towel.

CORRECTION: .

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00
Subtotal for Job #7:			17.00

Parts Total:	0.00
Labour Total:	204.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	204.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 03 Sep 2024

W/O: 74483
Promised Date: 31 AUG 24



Customer #: 1000
BASDENS AMERICAN RV,

