

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2023257
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CKEC7SY034972
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	095 / 095A
OWNER INFORMATION		ITEM #	CKT16EV-95
		DEALER RO #	74531
		CLAIM START DATE	08/15/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-95-01-00-000959	Free Standing Dinette Table - Interior/Dinette/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-08-15 11:22:08 :: SCRATCH ON DINETTE TABLE			
	SCRATCH ON DINETTE TABLE Tried to clean mark off with polish, but mark is too deep. 8/15/2024: Turned in			
	parts request for a new table. need to replace the table			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	20-66-24-00-000658	Entry Door - Exterior/Entry Doors/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-08-15 11:24:26 :: ENTRY AND SCREEN DOOR NEED			
	ADJUSTED ENTRY DOOR AND SCREEN DOOR NEED ADJUSTED Entry door dill not latch closed unless slammed			
	hard. Removed latch plate. Filled door frame to allow more adjustment. Drilled new mounting hole for screw.			
	Remounted latch plate on doorframe. Checked operation of door. Door now latches ok and opens ok.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$51.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$51.00
	Notes			
	repaired			

Labor

Line# 3	Operation Code	Operational Description		
	70-167-01-00-001997	Water Heater Door - Appliances/Water Heater (Suburban)/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-08-15 11:25:04 :: WH DOOR MOUNTING HINGE			
	BROKEN...NOTED AT TIME OF DELIVERY WATER HEATER DOOR MOUNTING BROKEN. NOTED AT TIME OF			
	DELIVERY Removed broken mounting lugs from door frame. Installed new water heater door. Adjusted water			
	heater mounting flange to allow door to close and lock.			
Model# sw7ec	Dlr Sub Hrs	0.30	Sub Labor Amt	\$51.00
Serial# 2428005947	Appr Hrs	0.30	Appr Labor Amt	\$51.00
	Notes			

Submitted	Labor Amt	\$119.00	Approved	Labor Amt	\$119.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$119.00		Total	\$119.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.