



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74531
Promised Date:
24 AUG 24

CUSTOMER WORK ORDER

WO #: 74531

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0830 BH TO CLOSE

Stock #: 11448
Stock Desc: 2025 TT FOREST RIVER
CHEROKEE WOLF PUP 16EV
Chassis #: 5ZT2CKEC7SY034972
Serial #: 5ZT2CKEC7SY034972
Mileage: 0
Licence:

Invoice #:
Date In: 14 AUG 24
Promised: 31 AUG 24
Date Sched:
Completed: 30 AUG 24
Warr. Date:

Job #PDINTT - Internal

Transferred to BAS*74663 on 28 AUG 24
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER - 3 HR PDI

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: SCRATCH ON DINETTE TABLE

CAUSE: SCRATCH ON DINETTE TABLE

CORRECTION: Tried to clean mark off with polish, but mark is too deep. 8/15/2024: Turned in parts request for a new table.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	17.00
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	0.00

Parts

Part #	Description	Qty	Price	Total
F100609716	COUNTERTOP, LW211 DINETTE TABLE TOP	1.00	83.49	83.49

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-TABLE	1.00	15.00	15.00

Subtotal for Job #1: 115.49

Job #2 - Warranty

COMPLAINT: ENTRY AND SCREEN DOOR NEED ADJUSTED



Customer #: 1000
BASDEN'S AMERICAN RV,





CAUSE: ENTRY DOOR AND SCREEN DOOR NEED ADJUSTED

CORRECTION: Entry door dill not latch closed unless slammed hard. Removed latch plate. Filled door frame to allow more adjustment. Drilled new mounting hole for screw. Remounted latch plate on doorframe. Checked operation of door. Door now latches ok and opens ok.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	51.00
Subtotal for Job #2:			51.00

Job #3 - Warranty

COMPLAINT: WH DOOR MOUNTING HINGE BROKEN...NOTED
AT TIME OF DELIVERY

CAUSE: WATER HEATER DOOR MOUNTING BROKEN. NOTED AT TIME OF DELIVERY

CORRECTION: Removed broken mounting lugs from door frame. Installed new water heater door.
Adjusted water heater mounting flange to allow door to close and lock.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	51.00

Parts				
Part #	Description	Qty	Price	Total
140066	6261AEB BLK WH DOOR - SUBURBAN SURFA	1.00	39.09	39.09
Subtotal for Job #3:				90.09

Parts Total:	122.58
Labour Total:	119.00
Sublet Total:	0.00
Extras Total:	15.00
WORK ORDER TOTAL:	256.58

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited
to work performed. Consequential damages are not covered. All guaranteed work
must be completed in our service department.

Customer Signature : _____

Date: 30 Aug 2024

