



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74533
Promised Date:
24 AUG 24

CUSTOMER WORK ORDER

WO #: 74533

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0830 CHECK PREAUTH

Stock #: 11450
Stock Desc: 2025 TT KEYSTONE
SPRINGDALE 260BHC
Chassis #: 4YDTSGL24S7100686
Serial #: 4YDTSGL24S7100686
Mileage: 0
Licence:

Invoice #:
Date In: 15 AUG 24
Promised: 31 AUG 24
Date Sched:
Completed: 29 AUG 24
Warr. Date:



Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*74666 on 28 AUG 24
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER - 4 HR PDI

CAUSE: PDINTT PDI - NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Installed new battery box. Moved LP tray forward to clear battery box. Filled LP tanks. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 75 psi. Checked roof and sealed a few spots. Checked power cord. Checked converter output. Operated all stab jacks. Checked awning. Checked all interior lights. Removed all packing from refrigerator and microwave. Checked all interior lights. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Checked all windows and blinds. Checked Refrigerator. Applied all company decals. Added water to fresh water tank and flushed antifreeze from Water pump. Connected to city water and flushed water lines and faucets. Filled all holding tanks and checked monitor panel. Performed LP drop test and set LP pressure at 10 in.wc. Checked Range, Water Heater and Furnace. Removed all winterizing stickers. Drained all holding tanks. Returned unit to sales lot.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: REAR COMPARTMENT DOOR LOCK IS OUT OF ALIGNMENT

CAUSE: REAR COMPARTMENT DOOR LOCK IS OUT OF ALIGNMENT

CORRECTION: Checked key lock on compartment door. Lock is loose and twisting when trying to lock. Straightened lock assembly on door and tightened mounting nut to secure to door. Lock now works ok.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	34.00

Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 34.00

Job #2 - Warranty

COMPLAINT: SHOWER SEALANT HAS COME LOOSE AND NEEDS RE-SEALED

CAUSE: SHOWER SEALANT HAS COME LOOSE AND NEEDS RE-SEALED

CORRECTION: Sealed top corner that was void of sealer.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	34.00

Subtotal for Job #2: 34.00

Parts Total: 0.00

Labour Total: 68.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 68.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 29 Aug 2024

W/O: 74533
Promised Date: 31 AUG 24



Customer #: 1000
BASDEN'S AMERICAN RV,

