

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 74543
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 55117 - KENNETH JENKINS
Address: 7082 W ST RD 66
RICHLAND, IN
47634
Phone: 812-549-6544

Stock Number: 2022 VALOR

VIN:

HIN:

SER#: 7M5FV3922NA006168

Mileage:

Work Order Comp: 30 SEP 24

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 15 AUG 24

Inv #: 410189

WO # Job # Description JOB INFORMATION

74543 1 KITCHEN AUTO VENT FAN COVER IS BUSTED. CUSTOMER CALLED SELLING
DEALER AND SPOKE WITH RANDY BROWN AT SOUTH HAVEN RV. NOTE: PUT
UNIT INSIDE DUE TO CRACKED VENT COVER.
.cracked lid
Installed new vent lid.

74543 6 THERE ARE SEVERAL TABS MISSING ON THE ENDS OF THE BLINDS. GO
THROUGH COACH TO VERIFY WHICH BLIND TABS NEED TO BE REPLACED.
FOUND 7 END CAPS ARE MISSING
INSTALLED NEW END CAPS ON THE BLINDS.

74543 13 CUSTOMER ADVISES THAT THE SHROUD OVER THE CENTER AIR CONDITIONER
IS LOOSE.
The screws was tight. I guess they are taking about where the
front half meets the rear doesn't snap together tight.

74543 2 22V512 RECALL FOR FABRIC FOR LIPPERT
'
Did not see any canvas coming loose from the rail edge.

74543 3 KITCHEN SLIDE DON'T SEAL PROPERLY WHEN THE ROOM IS OUT. THIS IS
ON THE ON FRONT SIDE. THERE IS ABOUT AN INCH GAP. THE BULB SEAL
ON THE FRONT SIDE OF THE ROOM IS NOT COMPRESSING AS TIGHTLY AS
THE REAR SIDE.
'
Adjusted front rail out about an inch the seal is compressing

Claim : 74543

 WO # Job # Description JOB INFORMATION

more . Each side measures close to 25 3/4 from flange to wall.

74543 4 CUSTOMER ADVISED THAT THE PANTRY DOOR POPPED OPEN AND THEN THE SLIDE ROOM WAS RAN OUT. IT CAUGHT THE DOOR AND PULLED THE TRIM OFF OF THE REAR SIDE OF THE OFF DOOR SLIDE. NOTE: THE WOOD TRIM FOR THE SLIDE ROOM IS IN THE REAR GARAGE (TOY HAULER) FLOOR. INSTALLED NEW SCREWS INTO THE FRAME FOR SLIDE ROOM HAD SEVERAL STRIP OUT SO I HAD TO REMOVE THEM AND INSTALL SOME MORE THEN I STAPLED THE FACIA ON.

74543 8 CUSTOMER ADVISES THAT THE REAR BATHROOM FAUCET IS LOOSE AND NEEDS TO BE TIGHTENED.
 .
 Tightened base for the faucet.

74543 10 CUSTOMER ADVISES THAT THE ENTRY DOOR STEPS ARE INSTALLED CROOKED. MANY TIMES THE STEPS WILL NOT LATCH ON THE LEFT SIDE WHEN THEY ARE FOLDED AWAY FOR STORAGE. THE OUTER DOOR FRAME FLEXES WHEN CLOSING THE DOOR WITH THE STEPS OUT.
 Step was off about 1/8th inch.
 I moved step and added screws. The step sets strait now. I also found the floor Matt can get pushed under the step when folded up and cause it to lift and pull screws up.

74543 14 23V701 RECALL FOR SOLAR
 .
 Completed recall on solar connector.

Part No	Job#	Description	PARTS	Qty	Price	Total
MA10A40002K	1	REPLACEMENT VENT LID - MAXX		1.00	56.99	56.99
14659	6	END CAP - LH		7.00	0.00	0.00
14660	6	EMD CAP RH		7.00	0.00	0.00
20747	13	A/C SHROUD - WHITE POLISHED		1.00	294.99	294.99

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.50	170.00	85.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.50	170.00	85.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.30	170.00	51.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	13	MISC LABOUR CODE (EXTERNAL)		0.50	170.00	85.00
Z990	13	MISC LABOUR CODE (EXTERNAL)		0.50	170.00	85.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	170.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.60	170.00	102.00

Claim : 74543

```

*****
Lab Code  Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      3  MISC LABOUR CODE (EXTERNAL)      0.38    170.00    64.60
Z990      3  MISC LABOUR CODE (EXTERNAL)      0.12    170.00    20.40
Z990      4  MISC LABOUR CODE (EXTERNAL)      0.20    170.00    34.00
Z990      8  MISC LABOUR CODE (EXTERNAL)      0.00    170.00     0.00
Z990      8  MISC LABOUR CODE (EXTERNAL)      0.10    170.00    17.00
Z990     10  MISC LABOUR CODE (EXTERNAL)      0.10    170.00    17.00
Z990     14  MISC LABOUR CODE (EXTERNAL)      0.50    170.00    85.00

```

```

*****
Excode    Job#  Description          EXTRAS          Qty      Price     Total
*****
FRT       1  FREIGHT              1.00      4.99      4.99
FRT      13  FED-EX - SHROUD      1.00     26.08     26.08

```

Parts Total: 351.98
Labour Total: 731.00
Sublet Total: 0.00
Extras Total: 31.07

>>>> Claim Total: 1,114.05

Customer Signature: _____

Date: _____