

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
BASDEN RV CENTER INC		<b>CLAIM</b>	2031284
DBA AMERICAN RV CENTER		<b>CLAIM ORIGIN</b>	WEB
600 E BASELINE ROAD		<b>ORIGINAL CLAIM ID</b>	
EVANSVILLE, IN 47725		<b>VIN</b>	5ZT2CARBXR030510
USA		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$170.00	<b>SITE/WAREHOUSE</b>	205 / 205
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	ACAT263BHSCKLE
SCOTT D BUEDEL		<b>DEALER RO #</b>	74560
10501 DENZER RD		<b>CLAIM START DATE</b>	08/21/2024
Evansville, IN 47720		<b>CLAIM END DATE</b>	01/01/1900
USA			
<b>Retail Date of Purchase</b>	03/16/2024	<b>WARRANTY EXPIRATION DATE</b>	03/16/2025

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	40-106-01-12-001216	Clearance Light - Electrical/12 Volt Exterior/Replace/Exterior Lighting		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2024-08-21 15:50:42 :: HALF OF THE MARKER LIGHTS ARE NOT WORKING ON THE UNIT I FOUND ONE OF THE CONNECTORS BEHIND THE RIGHT REAR TAIL LIGHT HAD GOTTEN HOT. IT MELTED THE CONNECTOR AND I REPLACE ALL 3 CONNECTORS AT THIS LOCATION.			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	1.00	<b>Sub Labor Amt</b>	\$170.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.60	<b>Appr Labor Amt</b>	\$102.00
	<b>Notes</b>			
	EXCESSIVE AMOUNT REQUESTED. CHANGED TO 3X FLAT RATE			

<b>Submitted</b>	<b>Labor Amt</b>	\$170.00	<b>Approved</b>	<b>Labor Amt</b>	\$102.00
	<b>Parts &amp; Freight</b>	\$0.00		<b>Parts &amp; Freight</b>	\$0.00
	<b>Total</b>	\$170.00		<b>Total</b>	\$102.00

**DEALER** \_\_\_\_\_ **DATE** \_\_\_\_\_

**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

**CUSTOMER** \_\_\_\_\_ **DATE** \_\_\_\_\_

**SIGNATURE**

All repairs described have been inspected and are satisfactory.