

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2075450
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKE27SX164845
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT29TE
		DEALER RO #	74623
		CLAIM START DATE	09/30/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase	WARRANTY EXPIRATION DATE
-------------------------	--------------------------

Claim Line Details			
Labor			
Line# 1	Operation Code	Operational Description	
	70-708-01-11-004503	Wall Plate - Appliances/Antenna (Winegard Air 360, Connect)/Replace/Electrical	
	Complaint, Cause, Correction		
	Original Note : bhoffman@americanrvcenter.com, 2024-09-30 11:37:11 :: FRONT BEDROOM ANTENNA COAX PLATE DAMAGED FRONT BEDROOM ANTENNA COAX PLATE DAMAGED TV coax will not go in antennaceiling plate. Inside of connector is off center keeping TV antenna coax from connecting to it. replaced ceiling plate and connector. Checked operation of new part. OK.		
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$85.00
Serial#	Appr Hrs	0.50	Appr Labor Amt \$85.00
Notes			

Submitted	Labor Amt	\$85.00	Approved	Labor Amt	\$85.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$85.00		Total	\$85.00

DEALER	DATE	CUSTOMER	DATE
SIGNATURE		SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.		All repairs described have been inspected and are satisfactory.	