



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 74623  
Promised Date:  
26 SEP 24



### CUSTOMER WORK ORDER

WO #: 74623

Customer: 1000 - BASDENS AMERICAN  
RV -  
Tag:  
Author: BH  
Location: 1005 CHECK PREAUTH

Stock #: 11459  
Stock Desc: 2025 TT FOREST RIVER  
CHEROKEE 29TE  
Chassis #: 4X4TCKE27SX164845  
Serial #: 4X4TCKE27SX164845  
Mileage: 0  
Licence:

Invoice #:  
Date In: 26 AUG 24  
Promised: 30 SEP 24  
Date Sched:  
Completed: 30 SEP 24  
Warr. Date:

#### Job #PDINTT - Internal

COMPLAINT: Transferred to BAS\*74897 on 30 SEP 24  
Estimate amount was 0.00  
PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT PDI - NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Filled LP tanks. Secured battery box to frame. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Applied all company decals. Operated all stab jacks. Checked power cord. Checked both entrance doors and all compartment doors. Removed all packaging material from outside kitchen. Checked power awning and lights. Checked all interior lights. Checked converter output. Checked Radio. Checked inside and outside Refrigerators. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Checked all cabinets and drawers. Checked all windows and blinds. Took pictures and recorded all serial numbers. Added water to fresh water tank. Flushed antifreeze from water pump. Connected to city water and flushed antifreeze from all water lines and faucets. Filled all holding tanks and checked monitor panel. Performed LP drop test and set LP pressure at 10 in.wc. Checked all antenna outlets with test TV. Checked Refrigerator, Range, Microwave, Furnace, Air Conditioner, outside Refrigerator, Ice Maker and Grille. Checked roof and sealed a few air bubbles. Moved unit back to sales lot.

Customer #: 1000  
BASDENS AMERICAN RV,



#### Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

**Subtotal for Job #PDINTT: 0.00**

#### Job #1 - Warranty

COMPLAINT: FRONT BEDROOM ANTENNA COAX PLATE DAMAGED

CAUSE: FRONT BEDROOM ANTENNA COAX PLATE DAMAGED

CORRECTION: TV coax will not go in antennaceiling plate. Inside of connector is off center keeping TV antenna coax from connecting to it. replaced ceiling plate and connector. Checked operation of new part. OK.

#### Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Z990 MISC LABOUR CODE (EXTERNAL) DKM 85.00

**Parts**

Part #	Description	Qty	Price	Total
357312	Plate - Coax - Single - Black	1.00	1.05	1.05

**Subtotal for Job #1: 86.05**

**Job #2 - Internal**

COMPLAINT: THE FRONT ENTRY DOOR IS HARD TO OPEN. (NOTED AT DELIVERY)

CAUSE: FRONT ENTRY DOOR IS HARD TO OPEN (NOTED AT DELIVERY)

CORRECTION: Removed latch plate from door frame. Filed outside edge of door to add more adjustment to latch plate. Remounted latch plate and checked operation of entrance door. Now opens better.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

**Subtotal for Job #2: 0.00**

Parts Total: 1.05

Labour Total: 85.00

Sublet Total: 0.00

Extras Total: 0.00

**WORK ORDER TOTAL: 86.05**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 04 Oct 2024

W/O: 74623  
Promised Date: 30 SEP 24



Customer #: 1000  
BASDEN'S AMERICAN RV,

