

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2045218
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CANB2RU043498
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT243RBSLE
DONALD E LITTLEPAGE		DEALER RO #	74634
4821 OVERLAND DR		CLAIM START DATE	09/03/2024
Newburgh, IN 47630		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	06/29/2024	WARRANTY EXPIRATION DATE	06/29/2025

Claim Line Details

Labor

Line# 1	Operation Code		Operational Description	
	20-43-19-00-001109		Gutter Rail - Exterior/Exterior Miscellaneous/Reseal/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-09-03 14:00:45 :: WATER IS LEAKING ABOVE THE ENTRY DOOR ON THE OUTSIDE MARKED WITH BLUE TAPE Gutter seam is leaking. Applied silicone.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00	
Serial#	Appr Hrs	0.20	Appr Labor Amt \$34.00	
Notes				

Labor

Line# 2	Operation Code	Operational Description		
	60-141-12-00-001592	Tub Surround to Wall, each section - Plumbing/Shower, Tub Surround/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-09-03 14:01:20 :: THE SEAL AT THE BOTTOM OF THE SHOWER IS NOT HOLDING WATER AND IT LETS IT RUN INTO THE FLOOR. Shower surround isn't sealed. Applied silicone as needed and removed excess.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00	
Serial#	Appr Hrs	0.20	Appr Labor Amt \$34.00	
	Notes			
	AUTHORIZED AS REQUESTED			

Labor

Line# 3	Operation Code	Operational Description		
	30-102-01-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-09-03 14:01:59 :: THERE IS TRIM ON THE CEILING IN THE BED ROOM HAS COME LOOSE AND YOU CAN SEE GAPS There are staples on thr track that the trim sits in. Removed staples and secured trim.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00
	Notes			

Labor

Line# 4	Operation Code	Operational Description
	30-100-24-00-001056	Backsplash - Interior/Cabinetry/Repair/No Tread Code
	Complaint, Cause, Correction	

Original Note : bhoffman@americanrvcenter.com, 2024-09-03 14:03:11 :: THE BACK SPLASH IS LOOSE AND IS FALLING OFF Applied contact adhesive to the wall. Sealed edge with silicone

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00

Notes
AUTHORIZED AS REQUESTED

Submitted	Labor Amt	\$119.00	Approved	Labor Amt	\$119.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$119.00		Total	\$119.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.