

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2065999
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CKEC5SY035148
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	095 / 095A
OWNER INFORMATION		ITEM #	CKT16BHSW-95
		DEALER RO #	74653
		CLAIM START DATE	09/20/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-66-02-17-000672	Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-09-20 10:54:29 :: ENTRY DOOR NEEDS ADJUSTED			
	ENTRY DOOR NEEDS ADJUSTED Adjusted latch on entry door frame.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

Labor

Line# 2	Operation Code	Operational Description		
	70-674-24-00-002001	Water Heater Door - Appliances/Water Heater - Tankless (Furrion)/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-09-20 10:55:35 :: SEALER ON WATER HEATER DOOR			
	SEALER ON WATER HEATER DOOR Cleaned sealer off of water heater mounting frame and door.			
Model# NA	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial# NA	Appr Hrs	0.00	Appr Labor Amt	\$0.00
Notes				
after review, Forest River denied claim line. Per pictures attached correct amount of sealant was installed inside the water heater				
Forest River didn't see issue with sealant on the water heater door				

Labor

Line# 3	Operation Code	Operational Description		
	30-474-12-00-003344	Bracket - Interior/Appliance Securement/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-09-20 10:56:55 :: OUTSIDE FRIDGE DOOR IS SCRATCHED			
	OUTSIDE REFRIGERATOR DOOR IS SCRATCHED Touched up scratches with black marker.			
Model# NA	Dlr Sub Hrs	0.50	Sub Labor Amt	\$85.00
Serial# NA	Appr Hrs	0.20	Appr Labor Amt	\$34.00
Notes				
after review, Forest River authorized dealer .20 please resecure the mini refrigerator and touch up refrigerator door				

Labor

Line# 4	Operation Code	Operational Description		
	40-106-01-00-001254	Scare Light - Electrical/12 Volt Exterior/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-09-20 10:57:35 :: ROADSIDE OUTSIDE SCARE LIGHT			
	BROKEN ROADSIDE OUTSIDE SCARE LIGHT BROKEN Housing around light switch broken. Removed damaged			

light. Cut power wires. Wired in new light and mounted on unit. Checked operation of light. Resealed around light housing.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00
Notes				

Submitted	Labor Amt	\$153.00
	Parts & Freight	\$0.00
	Total	\$153.00

Approved	Labor Amt	\$85.00
	Parts & Freight	\$0.00
	Total	\$85.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.