

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2045274
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKX25SK091792
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT22CE-94
		DEALER RO #	74654
		CLAIM START DATE	09/03/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-103-24-00-001136 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-09-03 14:11:09 :: ENTRY STEPS ARE HITTING DOOR FRAME ENTRY STEPS ARE HITTING DOOR FRAME Side stops are hitting door frame. Adjusted both side stops to clear door frame when opening and closing steps.	Operational Description Interior Step - Interior/Flooring/Repair/No Tread Code		
Model#		Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$34.00
Notes				

Labor

Line# 2	Operation Code 20-66-02-00-000678 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-09-03 14:21:41 :: SCREEN DOOR HITTING DOOR LATCH SCREEN DOOR HITTING DOOR LATCH Adjusted hinges on screen door to allow screen door to close and not hit door latch.	Operational Description Screen Door - Exterior/Entry Doors/Adjust/No Tread Code		
Model#		Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$34.00
Notes				

Labor

Line# 3	Operation Code 60-139-19-00-001562 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-09-03 14:22:20 :: SEALER ON KITCHEN SINK SEALER ON KITCHEN SINK Sealer smeared on front of kitchen sink. Cleaned off sealer with GOO GONE and Windex.	Operational Description Sink - Plumbing/Kitchen (Galley) Sink/Reseal/No Tread Code		
Model#		Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$34.00
Notes				

Labor

Line# 4	Operation Code 20-66-24-00-000658 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2024-09-03 14:23:16 :: ENTRY DOOR WILL NOT LATCH CLOSED ENTRY DOOR WILL NOT LATCH CLOSED Removed latch plate from door frame. Filed cut out in door frame to allow more adjustment of latch plate. Drilled new mounting holes for adjustment. Remounted latch plate Checked operation of door closing. Entrance door now closes OK.	Operational Description Entry Door - Exterior/Entry Doors/Repair/No Tread Code		
---------	--	---	--	--

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$51.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$51.00
Notes thank you				

Submitted	Labor Amt	\$153.00
	Parts & Freight	\$0.00
	Total	\$153.00

Approved	Labor Amt	\$153.00
	Parts & Freight	\$0.00
	Total	\$153.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.