



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74655



CUSTOMER WORK ORDER

WO #: 74655	Customer: 1000 - BASDEN'S AMERICAN RV -	Stock #: 11461	Invoice #:
Tag:	Author: PH	Stock Desc: 2025 TT FOREST RIVER CHEROKEE GREY WOLF 29QB	Date In: 28 AUG 24
Location: 0918 CHECK WORK		Chassis #: 4X4TCKE23SX164874	Promised:
		Serial #: 4X4TCKE23SX164874	Date Sched:
		Mileage: 0	Completed: 31 AUG 24
		Licence:	Warr. Date:

Job #PDINTT - Internal
COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT PDI - NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Removed LP tanks and filled. Installed new battery box. Connected to test battery and checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 65 psi. Operated all stab jacks. Checked roof. Checked power cord. Checked converter output. Checked awning. Checked inside and outside refrigerators. Checked all interior lights. Checked all windows and blinds. Checked all cabinets and drawers. Checked Air Conditioner. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Took pictures and recorded all serial numbers. Added water to fresh water tank. Flushed antifreeze from faucets and water lines. Connected to city water and flushed all water lines. Performed LP drop test and set LP pressure at 10 in.wc. Checked operation of Water Heater, Furnace and Range. Filled all holding tanks and checked monitor panel. Used test TV to check all Antenna locations. Applied all company decals. Checked both entrance doors and all compartment doors. Drained all holding tanks. Moved unit back to sales lot.

Labor			
Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts				
Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty
COMPLAINT: FRONT ENTRY DOOR AND SCREEN DOOR HITTING LATCH

CAUSE: FRONT ENTRY DOOR AND SCREEN DOOR HITTING LATCH

CORRECTION: Adjusted entry door striker plate and screen door latch. Checked operation after adjustment. Door and screen now closing ok.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	34.00

Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 34.00

Job #2 - Warranty

COMPLAINT: BATHROOM DOOR LEADING TO BEDROOM IS HITTING THE FRAME

CAUSE: BATHROOM DOOR LEADING TO BEDROOM IS HITTING THE FRAME

CORRECTION: Hinge screws at top of door are loose. Tightened hinge mounting screws. Door now closes without hitting frame.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	34.00

Subtotal for Job #2: 34.00

Job #3 - Warranty

COMPLAINT: REAR DOOR AND SCREEN DOOR HITTING FRAME

CAUSE: REAR DOOR AND SCREEN DOOR HITTING FRAME

CORRECTION: Adjusted screen door latch. Drilled new mounting holes for entrance door striker plate. Mounted striker plate in new holes. Checked operation of screen door and entrance door. Both now closing ok.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	34.00

Subtotal for Job #3: 34.00

Parts Total:	0.00
Labour Total:	102.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	102.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 03 Sep 2024

Customer Signature : _____

W/O: 74655



Customer #: 1000
BASDENS AMERICAN RV,

