

Claim Response

Claim: C3697030

Non-Warranty Goodwill Adjustment

Last Modified bystutk

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3697030	74689	9/12/2024	9/12/2024	4YDT26723LK415076		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	170.00	0.00	SA21-414	6/20/2020

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
			1.00	0.00	0.00	15.00	0.00	0.00	0.00	0.00	Approved

Marshall in unit

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442K	Safety Advisory	21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B Cause: lp regulator recall Correction: i removed the covor, and i inspected regulator and it did not need to be changed, so i took a picture, and there was no further action required		0.30	0.30	51.00	0.00	1	0.30	Approved

Submitted parts & subLet	0.00	Approved parts & subLet	0.00
Submitted labor & subLet	51.00	Approved labor & subLet	51.00
Submitted freight:	0.00	Approved freight:	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	<u>51.00</u>	Total approved:	<u>51.00</u>