



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74742
Promised Date:
24 SEP 24



CUSTOMER WORK ORDER

WO #: 74742

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 1018 CHECK WORK

Stock #: 11463
Stock Desc: 2025 5W KEYSTONE
COUGAR 320RDS
Chassis #: 4YDFCGR2XS2501478
Serial #: 4YDFCGR2XS2501478
Mileage: 0
Licence:

Invoice #:
Date In: 09 SEP 24
Promised: 30 SEP 24
Date Sched:
Completed: 10 OCT 24
Warr. Date: 04 OCT 24

Job #PDINFW - Internal

COMPLAINT: Transferred to BAS*74896 on 30 SEP 24
Estimate amount was 0.00
PDI - NEW FIFTH WHEEL

CAUSE: CHECKED ALL APPLIANCES. DOCUMENTED MODEL AND SERIAL NUMBERS. REMOVED
PACKAGING FROM APPLIANCES. TESTED ALL LIGHTS. FILLED L.P. RAN L.P. DROP TEST. TESTED
ELECTRICAL AND PLUMBING SYSTEMS. FILLED AND DRAINED HOLDING TANKS. CHECKED
DRAWERS AND CABINETS. CHECKED TIRE PRESSURE. TORQUED LUG NUTS. CHECKED LEVELING
SYSTEM.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: FAN SWITCH IS BROKEN

CAUSE: Fan switch wouldn't latch to mounting screws. Repositioned screws and secured switch.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	34.00

Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 74742
Promised Date: 30 SEP 24

Customer #: 1000
BASDEN'S AMERICAN RV,

Subtotal for Job #1: 34.00

Job #2 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED

CAUSE: Placed wooden block on bottom of door to push flange out.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	34.00

Subtotal for Job #2: 34.00

Job #3 - Warranty

COMPLAINT: TV IS NOT PICKING UP CHANNELS

CAUSE: Ran channel scan. TV says weak or no signal. Located Key TV booster. Removed panel from wall and checked connections. Removed coax wires and tested continuity. Coax leading to both tv inputs are good. Removed fireplace to gain access to coax going under entertainment center. Small piece of insulation on the coax jumper wire from TV to cable inlet. Installed new fitting. Coax jumper has continuity. Ran channel scan. Still have no signal. Took test TV and ran in bedroom. Bedroom picked up channels. Removed splitter inside entertainment center. Hooked up a good coax cable and tested. Open circuit inside splitter.

CORRECTION: Donnie was able to fix issue.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	79.90
Z990	MISCELLANEOUS REPAIR	ZMS	59.50
Z990	MISCELLANEOUS REPAIR	ZMS	30.60
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	85.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
540721	Cable - Coax - Diplexer - w/Interior	1.00	7.87	7.87

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-CABLE PLATE	1.00	18.60	18.60

Subtotal for Job #3: 281.47

Parts Total:	7.87
Labour Total:	323.00
Sublet Total:	0.00
Extras Total:	18.60
WORK ORDER TOTAL:	349.47

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Oct 2024

W/O: 74742
Promised Date: 30 SEP 24



Customer #: 1000
BASDEN'S AMERICAN RV,

