



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74757
Promised Date:
20 SEP 24



Customer #: 54800
RAMIREZ, DANIEL



CUSTOMER WORK ORDER

WO #: 74757 (Appointment Date: 11 SEP 2024 - Time: 07:00pm)

Customer: 54800 - RAMIREZ, DANIEL -
956-422-0047

Tag: BH - PARTS ORDERED. 9-19-24

Author: BH

Location: 0926 CHECK STATUS WITH

SAR

Stock #: 11384

Stock Desc: 2024 TT KEYSTONE

SPRINGDALE 310BR

Chassis #: 4YDTSGR21R7104499

Serial #: 4YDTSGR21R7104499

Mileage: 0

Licence:

Invoice #:

Date In: 11 SEP 24

Promised: 30 SEP 24

Date Sched:

Completed: 25 SEP 24

Warr. Date: 31 MAY 24

Job #1 - Warranty

COMPLAINT: WATER HEATER IS NOT WORKING NOT WORKING ON GAS

CAUSE: The control board for the water heater is burnt, I found that the blue wire going to the touch pad is shorted in the trailer some where. Best thing to do is cap wire off and run new wire from water heater to touch pad In bathroom.

Wires ground out

CORRECTION: Received the new thermostat and control board for the water heater . Unscrewed and unplugged the control board from the water heater . Put the new control board in then put the screws back in and plugged in . With checking contuity on the wires from the water heater to the thermostat , both wires had contuity but was disconnected from the water heater and thermostat . Dropped the underbelly and the lp line on the doorside . Ran new wires from the water to the thermostat thru the underbelly . Connected the wires at the water heater and thermostat then tested the water heater for hot water . Put the underbelly back up then mounted the lp line back up . Took pictures of the process .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	510.00
Z990	MISCELLANEOUS REPAIR	BRM	119.00
Z990	MISCELLANEOUS REPAIR	BRM	0.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
492982	Water Heater - Control Panel - For G	1.00	27.31	27.31
682879	Water Heater - Control Board - New S	1.00	244.92	244.92

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00
FRT	FREIGHT	1.00	23.20	23.20

Subtotal for Job #1: 924.43

Job #2 - External

COMPLAINT: REPLACE ENTRY DOOR GIVE PRICE OF NEW DOOR

CAUSE: BH CALLED CUSTOMER \$1800 TO FIX DOOR CUSTOMER DECLINED 9-11

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C



W/O: 74757
Promised Date: 30 SEP 24



Customer #: 54800
RAMIREZ, DANIEL



Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT-DOOR & DECALS	0.00	N/C	N/C
Subtotal for Job #2:				0.00

Job #3 - Internal

COMPLAINT: THE FRONT A/C IS NOT WORKING RIGHT ON FAN HIGH AND AUTO AND FREEZING UP

CORRECTION: MOVED THE FAN BLADE ON THE SHAFT EWEY ONCE IN AWHILE IT WOULD MOVE AND RUB THE INSIDE SHROUD.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	N/C
Z990	MISCELLANEOUS REPAIR	BRM	N/C
Subtotal for Job #3:			0.00

Job #4 - Internal

COMPLAINT: THE REAR A/C IS NOT WORKING RIGHT ON FAN HIGH AND AUTO AND FREEZING UP

CORRECTION: CHECKED THE FAN BLADE AND MADE SURE IT WAS TIGHT ON MOTOR.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	N/C
Z990	MISCELLANEOUS REPAIR	BRM	N/C
Z990	MISCELLANEOUS REPAIR	BRM	N/C
Z990	MISCELLANEOUS REPAIR	BRM	N/C
Subtotal for Job #4:			0.00

Job #5 - Internal

The I in Springdale on door side is missing

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
696980	Diecut - 2023 - SG - Side/Rear - Spr	1.00	N/C	N/C
Subtotal for Job #5:				0.00

Parts Total: 272.23
Labour Total: 629.00
Sublet Total: 0.00
Extras Total: 23.20
WORK ORDER TOTAL: 924.43

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 01 Oct 2024

