



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74872
Promised Date:
20 SEP 24



CUSTOMER WORK ORDER

WO #: 74872

Customer: 20296 - DEUTSCH, STEVEN -
812-454-2007

Tag:

Author: BH

Location: 1025 CHECK WORK

Stock #: 11272

Stock Desc: 2024 5W KEYSTONE

COUGAR HALF-TON 25RES

Chassis #: 4YDFCGL23RV501808

Serial #: 4YDFCGL23RV501808

Mileage:

Licence:

Invoice #:

Date In: 26 SEP 24

Promised: 30 SEP 24

Date Sched:

Completed: 22 OCT 24

Warr. Date: 30 SEP 24

Job #MAXX - Internal

COMPLAINT: ROOF VENT COVER - INSTALLED EACH VENT COVER OVER BATHROOM

CAUSE: install roof vent over bathroom

CORRECTION: put on cover and marked for brackets and drilled holes and secured brackets then secured vent lid.

Labor

Code	Description	Mechanic	Total
Z990	INSTALL MAXX AIR VENT	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
40431	CAMCO VENT COVER - WHITE	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #MAXX: 0.00

Job #1 - Internal

COMPLAINT: INSTALL GEN Y PIN BOX

CAUSE: Install gen y pin box
gen y hitch

CORRECTION: Tried to install titch after removing old hitch I put new one in and it did not fit properly it was not the correct part I get with parts to get the correct one and put the old hitch back on and moved to wash bay 9-27-24

First I made sure that the hitch was the correct pin box the removed old pin box and put new one in and tightened bolts down to 151 foot pounds

had to drop hitch down 2 holes, installed new grade 8 bolts nuts and washers, torqued all bolts to 230 foot pounds.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
7066	GEN-Y EXECUTIVE FIFTH TO GOOSENECK C	1.00	N/C	N/C

Customer #: 20296
DEUTSCH, STEVEN



Subtotal for Job #1: 0.00**Job #2 - Internal**

SWAP MATTRESS W/ TRADE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JG	N/C

Subtotal for Job #2: 0.00**Job #FPDINFW - Internal**

COMPLAINT: FINAL PDI ON NEW FIFTH WHEELS

CAUSE: final pdi

CORRECTION: did final and everything on sheet ,and checked lp,water,electrical,and appliances.

Labor

Code	Description	Mechanic	Total
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	DGH	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	DGH	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	DGH	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	DGH	N/C
PDINFW	FINAL PDI NEW FIFTH WHEEL (INTERNAL	DGH	N/C

Parts

Part #	Description	Qty	Price	Total
SRM27	GROUP 27 DC BATTERY	1.00	N/C	N/C
14-0823	TITAN PULL PIN & CLIP	1.00	N/C	N/C

Subtotal for Job #FPDINFW: 0.00**Job #3 - Warranty**

COMPLAINT: OUTSIDE SHOWER KNOB FELL OFF

CAUSE: outside shower knob shot off.

CORRECTION: cold side knob shot off,i put back on and water would still run and not shut off on hot or cold,got new outside shower,took out all screws and cut silicone and pulled out shower,cleaned around opening,put putty tape around new housing and put in hole and secured,hooked up water lines,tested and no leaks.siliconed around box.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	0.00
Z990	MISCELLANEOUS REPAIR	DGH	510.00
Z990	MISCELLANEOUS REPAIR	DGH	0.00

Parts

Part #	Description	Qty	Price	Total
10-0843	DF-SA170-BK BLACK SHOWER BOX	1.00	49.11	49.11

Subtotal for Job #3: 559.11**Job #4 - Warranty**

COMPLAINT: FIRE PLACE FAN IS MAKING NOISE

CAUSE: Fireplace fan making noise

CORRECTION: Took off glass and screws and pulled out fireplace and took off back cover and found



fantastic hitting wire,pulled out wire and no more sound, put back on and reinstalled fireplace and secured and installed glass and secured.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DGH	51.00
Subtotal for Job #4:			51.00

Job #5 - Internal

COMPLAINT: CUSTOMER WOULD LIKE TO HAVE THE OVERHANG OF THE TRAILER SET ABOUT 3 INCHES HIGHER ABOVE THE BED RAILS THAN WHAT IT CURRENTLY IS.

CAUSE: Donnie adjusted the hitch

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
GNXA4085	GNXA4085 4" OFFSET GOOSENECK ADAPTER	1.00	N/C	N/C

Subtotal for Job #5: 0.00

Parts Total: 49.11
Labour Total: 561.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 610.11

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Oct 2024

W/O: 74872
Promised Date: 30 SEP 24



Customer #: 20296
DEUTSCH, STEVEN

