



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74926
Promised Date:
24 OCT 24



CUSTOMER WORK ORDER

WO #: 74926 (Appointment Date: 03 OCT 2024 - Time: 07:00am)

Customer: 30766 - WILL, TAMMY L -
(812) 453-6507

Tag: BJ - PARTS ORDERED. 10-4-24

Author: BJW

Location: 1016 SEE IF PARTS ARE
HERE YET

Stock #:

Stock Desc: 2022 KEYSTONE FUZION

Chassis #:

Serial #: 4YDFFZT29NF810321

Mileage:

Licence:

Invoice #: 410371

Date In: 03 OCT 24

Promised: 31 OCT 24

Date Sched:

Completed: 10 OCT 24

Warr. Date:

Job #ROOFT - External

COMPLAINT: INSPECT ROOF AND ROOF SEAMS - CLEAN AND FILL VOIDS. 1 TUBE OF ROOF
SEALANT INCLUDED.

CAUSE: Roof inspection

CORRECTION: Inspected the roof found just a few pin holes the the sealer around vents , skylights ,
antenna and roof edges. Cleaned and applied dicor sealer as needed to areas. Roof sealer and roof
membrane is in healthy condition.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #ROOFT: 0.00

Job #PACK2 - External

COMPLAINT: REPACK BEARING - DOUBLE AXLE TRAILER
INCLUDES INSPECT BRAKE SHOES, BEARINGS AND MAGNETS, ADJUST AS NEEDED

CAUSE: Bearing repack and damaged brake drums and backing plates

CORRECTION: Jacked up the camper then unbolted the wheels followed by the dust caps and the spindle
nut. Cleaned the spindles and bearings. Got with DENNY and Bj about damaged brakes and brake drums.
Put in po sheet for new brake drums and backing plates. Received the new backing plates and brake
drums. Setup on another job line. Mounted the wheels to the axles then adjusted each brake then tested
again. Set camper on the ground then torqued the lug nuts to 110ftlbs.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services


Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #PACK2: 0.00

Customer #: 30766
WILL, TAMMY L



W/O: 74926
Promised Date: 31 OCT 24



Customer #: 30766
WILL, TAMMY L



Job #22-423 - Warranty

COMPLAINT: RECALL 22-423 KEYSTONE SOLAR CONTROLLER WIRING

CAUSE: Correct connection where made

CORRECTION: Received the paperwork for solar recall then took pictures as necessary for recall. All numbers were correct as noted in paperwork.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	51.00
Subtotal for Job #22-423:			51.00

Job #22-437 - Warranty

COMPLAINT: Transferred to BAS*74983 on 09 OCT 24

Estimate amount was 0.00

22-437 EQUALIZER JACK PADS RECALL

CAUSE: Tightened bolts

CORRECTION: Set jack stands under the front of the toy hauler. Raised up the front jacks and lower the four rear jacks. Used a 1/2 Allen so ket to check for tightening on all 6 hydraulic jacks. No blue lock tight was needed. Lowered the front jacks then removed the jack stands.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	0.00
Subtotal for Job #22-437:			0.00

Job #23-439 - Warranty

Transferred to BAS*74984 on 09 OCT 24

Estimate amount was 0.00

23-439 FUEL PUMP CONTROLLER RECALL

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	0.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-BOX COVER	0.00	22.51	0.00
Subtotal for Job #23-439:				0.00

Job #24-452 - Warranty

COMPLAINT: Transferred to BAS*74985 on 09 OCT 24

Estimate amount was 0.00

SUBURBAN STOVE LIGHTS RECALL

CAUSE: Lights on the stove

CORRECTION: Pulled up the stove top the followed the instructions on disconnecting the lights from the stove. Took pictures of the process then put the stove top back together.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	SAR	0.00
Z990	MISCELLANEOUS REPAIR	SAR	0.00



Subtotal for Job #24-452: 0.00

Job #1 - External

COMPLAINT: REPLACE DAMAGED BRAKE PARTS FOUND DURING REPACK.

CAUSE: Brake drums and backing had damage from excessive wear

CORRECTION: Received the new brake drums and backing plates. Unboxed all parts to verify they were correct. Unbolted the damaged backing plates and cut the power from the brakes. Mounted the new brakes and torqued to spec. Wired in the electric brakes and tested the magnet. Packed new grease in the new brake drums with new seals. Mounted the brake drums and tightened then put on the dust cap.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
9921	BACKING PLATE KIT (1LH/1RH) 12"	2.00	N/C	N/C
9923	BRAKE DRUM/HUB	4.00	N/C	N/C

Subtotal for Job #1: 0.00

Parts Total: 0.00
Labour Total: 51.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 51.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Oct 2024

W/O: 74926
Promised Date: 31 OCT 24

Customer #: 30766
WILL, TAMMY L

