

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2162025
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAKB1SU044670
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT211BH-8
		DEALER RO #	74933
		CLAIM START DATE	01/02/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor

Line# 1

Operation Code	40-106-24-11-001253	Operational Description
		Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical
Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2025-01-02 13:13:12 :: PASSENGER TAIL LIGHT NOT WORKING Off door side turn light not working I pulled light off wall and found that one of the wires was not connected i then connected and remounted on the wall	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.40	\$68.00
Serial#	Appr Hrs	Appr Labor Amt
	0.40	\$68.00
Notes	AUTHORIZED AS REQUESTED	

Labor

Line# 2

Operation Code	10-5-01-11-000133	Operational Description
		Electric Landing Leg Motor - Frame & Chassis/Pin Box, Landing Gear & Hitch Assembly/Replace/Electrical
Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2025-01-02 13:14:00 :: BOTH SETS OF ELECTRIC JACKS ARE NOT WORKING Jacks not working The front would only run the door side then the rear would only run the off door side i then made sure that both motors had power going to them and they all did but we're not working	
Model#	Dlr Sub Hrs	Sub Labor Amt
	1.00	\$170.00
Serial#	Appr Hrs	Appr Labor Amt
	1.00	\$170.00
Notes	NEED TO KNOW THE CORRECTION. NEED TO REPLACE THE MOTORS PENDING VND REVIEW AUTHORIZED BY VND VCB BAL R&R of the motor is 0.50 per motor flat rate. No Pre-auth required, please send the parts back for testing	

Labor

Line# 3

Operation Code	60-136-01-00-001480	Operational Description
		City Water Connection - Plumbing/Fresh Water Supply/Replace/No Tread Code
Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2025-01-02 13:15:12 :: CITY WATER LEAKING City water leaking I first remov3d screws holding the city water conection and I removed it then replaced with new and pit putty tape around the back and screwed into place and made sure it was not leaking	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.30	\$51.00
Serial#	Appr Hrs	Appr Labor Amt
	0.30	\$51.00
Notes		

Labor

Line# 4

Operation Code

50-134-12-00-003673

Operational Description

Rubber LP Supply Line - LP Gas/LP Gas System/Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-01-02 13:15:34 :: DURING LP LEAKDOWN TEST, TECH FOUND UNIT WILL NOT HOLD PRESSURE After doing lp drop test found there was a leak I first turned gas on and spraided lines conected to the tanks and found that one of the lines going to the tank was not fully tightened so I tightened and then did an lp drop test to be sure there was no more leak

Model#

Dlr Sub Hrs

0.10

Sub Labor Amt \$17.00

Serial#

Appr Hrs

0.10

Appr Labor Amt \$17.00

Notes

Submitted

Labor Amt

\$306.00

Parts & Freight

\$0.00

Total

\$306.00

Approved

Labor Amt

\$306.00

Parts & Freight

\$0.00

Total

\$306.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.