



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74938
Promised Date:
24 OCT 24

CUSTOMER WORK ORDER

WO #: 74938

Customer: 1000 - BASDENS AMERICAN
RV -
Tag:
Author: PH
Location: 1024 PH TO CLOSE

Stock #: 11480
Stock Desc: 2025 TT KEYSTONE
COUGAR HALF-TON 22MLS
Chassis #: 4YDTCGK2XSV502187
Serial #: 4YDTCGK2XSV502187
Mileage: 0
Licence:

Invoice #:
Date In: 03 OCT 24
Promised: 31 OCT 24
Date Sched:
Completed: 24 OCT 24
Warr. Date:



Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Checked appliances brakes tire pressure torqued lugs checked electrical system and plumbing system. Checked cabinets doors and drawers. Filled l.p and ran l.p leak test. Documented model and serial numbers.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C
10-1211	20183 3-PK 1" HOSE FILTERS	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Ran a.f through all lines and fixtures. Drained all tanks.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	ZMS	N/C

Parts



Customer #: 1000
BASDENS AMERICAN RV,



Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: THE TELEVISION IS NOT PICKING UP CHANNELS

CAUSE: Ran channel scan and couldn't pick up channels. Removed Outside plate to access antenna cable. Went inside and removed plate from ceiling to check cable. Coax cable is not there. Tried reaching my hand around but couldn't feel anything. Took a long pick tool and was able to pull cable through the ceiling. Cable end was damaged and had insulation around the copper. Replaced cable end and ran a channel scan on the TV. TV is now picking up channels. Installed wall and ceiling plates.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	170.00

Subtotal for Job #1: 170.00

Job #2 - Warranty

COMPLAINT: LP TANK BENT

CAUSE: L.p tank handle is bent. Replace?

CORRECTION: .REPLACED L.P. TANK. TANK HAS BEEN FILLED.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	15.30
Z990	MISCELLANEOUS REPAIR	ZMS	1.70

Parts

Part #	Description	Qty	Price	Total
66-4905	L.P.CYLINDER 20 LB. PW	1.00	63.91	63.91

Subtotal for Job #2: 80.91

Job #3 - Warranty

COMPLAINT: ADJUST ENTRY STEPS. DOOR HITTING FRAME

CAUSE: Entry step latch is hitting door frame. Loosened latch. Repositioned latch.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	17.00

Subtotal for Job #3: 17.00

Job #4 - Warranty

COMPLAINT: ENTRANCE DOOR LATCH HITTING

CAUSE: Moved latch over so door will clear latch

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	17.00



W/O: 74938
Promised Date: 31 OCT 24



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #4: 17.00

Parts Total: 63.91
Labour Total: 221.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 284.91

W/O: 74938
Promised Date: 31 OCT 24

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 24 Oct 2024



Customer #: 1000
BASDEN'S AMERICAN RV,

