

aim Response

10/21/2024
04:08:37 pm

Non-Warranty Goodwill Adjustment

Last Modified by: C2275

aim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed Type	Date Of Purcha
716646	75004	10/21/2024	10/21/2024	4YDT28724LT432085	1194	Basden's American RV	600 E Baseline Rd Evansville, IN 47725	170.00	0.00	SA21-414 9/15/20

ny Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Parts Under Review

ny Item number	Operation	Description	Srvc advisory	Sub hours	Apv'd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B		Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION: 71 COMPONENT: 414 OPERATION: 7141442B Cause: Lp regulator replacement Correction: Took pictures then received a new lp regulator from the warranty department. Shut off the lp tanks then removed the lp regulator. Put pipe dope on the lp hose then connected the new lp regulator. Connected the lp hose the lp tanks then checked for leaks. No leaks found.		0.50		0.00	0.00	1	0.50	Pending approval

Submitted parts & sublet	28.75	Approved parts & sublet	0.00
Submitted labor & sublet	85.00	Approved labor & sublet	0.00
Submitted freight:	0.00	Approved freight:	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	113.75	Total approved:	0.00