

Claim Response

Claim: C3714460

Non-Warranty Goodwill Adjustment

Last Modified byC2275

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3714460	75011	10/16/2024	10/16/2024	4YDT30329L3101488		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	170.00	0.00	SA21-414	8/8/2020

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	696405	Regulator - Recall Only Kit - A	1.00	0.00	25.00	15.00	28.75	0.00	0.00	0.00	Parts Under Review

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: KEYSTONE SAFETY ADVISORY LP REGULATOR RECALL #21-414 SECTION:71 COMPONENT:414 OPERATION:7141442B Cause: lp regulator recall Correction: i inspected lp regulator and it fell under the category of it needed to be changed so i changed out with certified replacement		0.50		0.00	0.00	1	0.50	Pending approval

Submitted parts & subLet 28.75
Submitted labor & subLet 85.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 113.75

Approved parts & subLet 0.00
Approved labor & subLet 0.00
Approved freight: 0.00
Tax: 0.00
Total approved: 0.00