



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75110
Promised Date:
21 OCT 24

CUSTOMER WORK ORDER

WO #: 75110

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 1025 BH TO CLOSE

Stock #: 11484
Stock Desc: 2025 TT COACHMEN
CATALINA 303RKDSLE
Chassis #: 5ZT2CAVB4SX033236
Serial #: 5ZT2CAVB4SX033236
Mileage: 0
Licence:

Invoice #:
Date In: 18 OCT 24
Promised: 31 OCT 24
Date Sched:
Completed: 25 OCT 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: Went to parts department and got a new battery box and 2 20 lb lp tank fill, then filled those tanks. Mounted the lp tanks. Drilled holes in the battery box and mounted at the tongue. Setup a used battery to check the lights and brakes. Checked and set tire psi to 80 as noted, torqued the lug nuts to 110ftlbs. Ran the tongue jack up and down. Jacked up the camper, then tested the running lights, brakes, breakaway switch. Plugged in the shore power then turned the fridges on to chill. Leveled the camper. Checked the stove and griddle as well. Tested lp detector and smoke alarms. Went thru out the camper and checked the blinds and windows, vents, fans, doors, bedroom closet door hits the door frame. Checked the gfci outlets and usb outlets, got the test TV checked the antenna signal and the radio. Ran the awning out and in with the awning lights on and off. Checked the entry door handle and entry door latch. Adjusted the entry steps after camper was leveled. Ran the sliderooms out. Turned the AC on and let it run for 1hr. Tested the recliners with usb charging, dinette table, closet sliding mirror doors, master bed lift gate and all the cabinet doors. Powered on the fireplace and let it run for 20 minutes. Tested microwave, checked the converter output. Took pictures of the appliances and other items then filled out the paperwork. Removed the pins holding the gear rack to fill the fresh tank to 2/3 full then dewinterize the camper, turned the water pump on and filled the water heater. Connected the hose to the city water connection opened the kitchen faucet, bathroom faucet, toilet, shower, outside shower, washer connections, low points. Hooked up the manometer to the doorside rear kitchen then did the lp drop test with the furnace and water heater running. Hooked up the sewer hose to drain the black 1 tank and grey 1 and 2 tanks. Shut off the lp tanks and removed the test battery. Went on the roof and inspected the sealer and roof membrane.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z991	MISC LABOUR CODE (INTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 75110
Promised Date: 31 OCT 24



Customer #: 1000
BASDEN'S AMERICAN RV,



Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterizing

CORRECTION: Drained the black, grey, fresh tanks and the water heater. Went to the water heater and water pump and turned the valves. Added 3 gallons thru the kitchen faucet, bathroom faucet, toilet, shower, outside shower, washer connections and the low points. Depressed the city water connection. Dump any extra antifreeze from the 3 gallons down the drains.

Labor			
Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	SAR	N/C

Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Internal

COMPLAINT: FRIDGE DOOR HAS A SMALL DENT

CAUSE: Dent

CORRECTION: Took pictures of the dent in the fridge, Ben said carry on. No action required

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CLOSET DOOR IS HITTING DOOR FRAME

CAUSE: Door frame was to tight

CORRECTION: Unscrewed the door and latch plate from the door frame then cut off the extra paneling. Trimmed the door frame till the door shut with clearance. Screwed the door back on the door frame and the latch plate. Cleaned up the mess. Took pictures of the process.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	34.00

Subtotal for Job #2: 34.00



W/O: 75110
Promised Date: 31 OCT 24



Customer #: 1000
BASDEN'S AMERICAN RV,



Parts Total:	0.00
Labour Total:	34.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	34.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 25 Oct 2024

Customer Signature : _____

