



Warranty Authorization Form

Date: 11/12/2024

General Information

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200

Pre-Auth #: 77897 Unit: 7M5TD3321SC304564
Series: Delta Model: 2025DEL292RL
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 22561 TERMINATION VALVE - REPLACE - VALTERRA
(Photo of valve in open position is required)

Fault Code: LEAKS

Serial #:

Model #:

Notes:

Problem: BLACK TANK VALVE WILL NOT CLOSE

Time Requested: 10

Cause: BLACK TANK VALVE WILL NOT CLOSE

Time Allowed: 2.5

Remedy: Cut holes in underbelly for access to black tank valve. Found valve ,but will have to cut a bigger hole to remove tank valve. Cut a larger hole in underbelly for access to dump valve. Removed screws holding dump valve to black tank but drain pipes can not be spread apart to get valve out. Will have to cut two smaller drain pipes to get valve out. Cut both 1 1/2 grey tank drains lines to get dump valve out. The bottom of knife blade groove is full of glue, plus both valve seals are in the glue. Complete valve needs replaced. Turned in parts request for a new valve assembly. Cleaned glue off of seal flange. Checked Living Room TV and all other antenna outlets.

Sublet Repairs: 0.00

10/28/2024: Received new dump valve. Connected old cable pull to new dump valve. Placed valve into position next to black tank drain. Put drain outlet with connecting pipes in place with new dump valve. Installed valve mounting bolts and tightened securely. Checked operation of new valve with cable pull. Reconnected other drain pipes with fernco pipe connectors. Remounted drain pipe assembly supports. Filled all holding tanks and checked all new drain connections for leaks. No leaks found. Cut underbelly material to fit cutout for repair of plumbing. Added wood strips around edge of hole in underbelly and secured to cutout. Cut a new underbelly material to fit repair hole. Secured in place with screws and washers. Covered all cuts and screws in underbelly with roof seam tape. Painted all roof seam tape black. Filled gap around plumbing drain outlet with spray foam. Painted all spray foam black.

Part Return Req: No

Status: Approved with Modifications

Operation Line 2*Flat Rate Code:* 14015 CABINET - DOOR - ADJUST*Fault Code:* LOOSE*Serial #:**Model #:**Notes:**Problem:* CABINET DOOR LOOSE ABOVE THE REAR COUCH*Time Requested:* .1*Cause:* CABINET DOOR LOOSE ABOVE THE REAR COUCH (NOTED AT DELIVERY)*Time Allowed:* .1*Remedy:* Tightened hinges on both center doors above rear couch.*Sublet Repairs:* 0.00*Part Return Req:* No*Status:* Approved