



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75115
Promised Date:
20 NOV 24



CUSTOMER WORK ORDER

WO #: 75115

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 1107 CHECK PREAUTH

Stock #: 11489
Stock Desc: 2025 TT ALLIANCE RV
DELTA 292RL
Chassis #: 7M5TD3321SC304564
Serial #: 7M5TD3321SC304564
Mileage: 0
Licence:

Invoice #:
Date In: 18 OCT 24
Promised: 30 NOV 24
Date Sched:
Completed: 12 NOV 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*75336 on 05 NOV 24
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT PDI - NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Filled LP tanks. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Checked entrance door and all compartment doors. Checked both awnings. Operated all stab jacks. Checked roof and sealed a couple of voids. Checked power cord. Checked all interior lights. Checked all windows and blinds. Checked all cabinets and drawers. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Checked converter output. Removed shipping material from all appliances. Took pictures and recorded all serial numbers. Applied all company decals. Added water to fresh water tank and flushed antifreeze from water system. Checked all faucets and water lines for leaks. Operated all appliances. Performed LP drop test and set LP pressure at 10 in.wc.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: CABINET DOOR LOOSE ABOVE THE REAR COUCH

CAUSE: CABINET DOOR LOOSE ABOVE THE REAR COUCH (NOTED AT DELIVERY)

CORRECTION: Tightened hinges on both center doors above rear couch.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	17.00

Customer #: 1000
BASDEN'S AMERICAN RV,





Job #WINTER - Internal

COMPLAINT: Transferred to BAS*75336 on 05 NOV 24
Estimate amount was 0.00
WINTERIZE UNIT AND DRAIN HOLDING TANKS.
INCLUDES 2 GALLONS OF ANTI-FREEZE
UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA
DE-WINTERIZATION IS NOT INCLUDED
NUMBER OF GALLONS USED _____

CAUSE: WINTER WINTERIZE UNIT AND DRAINALL HOLDING TANKS *** INCLUDED 2 GALLONS OF ANTIFREEZE

CORRECTION: Blew out all water lines and faucets. Added antifreeze to all water lines and faucets, including (3) outside shower locations. Poured antifreeze in all drain traps. Drained all holding tanks.

Labor				
Code	Description		Mechanic	Total
Z990	WINTERIZE UNIT		DKM	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #2 - Warranty

COMPLAINT: BLACK TANK VALVE WILL NOT CLOSE

CAUSE: BLACK TANK VALVE WILL NOT CLOSE

CORRECTION: Cut holes in underbelly for access to black tank valve. Found valve ,but will have to cut a bigger hole to remove tank valve. Cut a larger hole in underbelly for access to dump valve. Removed screws holding dump valve to black tank but drain pipes can not be spread apart to get valve out. Will have to cut two smaller drain pipes to get valve out. Cut both 1 1/2 grey tank drains lines to get dump valve out. The bottom of knife blade groove is full of glue, plus both valve seals are in the glue. Complete valve needs replaced. Turned in parts request for a new valve assembly. Cleaned glue off of seal flange. Checked Living Room TV and all other antenna outlets. 10/28/2024: Received new dump valve. Connected old cable pull to new dump valve. Placed valve into position next to black tank drain. Put drain outlet with connecting pipes in place with new dump valve. Installed valve mounting bolts and tightened securely. Checked operation of new valve with cable pull. Reconnected other drain pipes with fernco pipe connectors. Remounted drain pipe assembly supports. Filled all holding tanks and checked all new drain connections for leaks. No leaks found. Cut underbelly material to fit cutout for repair of plumbing. Added wood strips around edge of hole in underbelly and secured to cutout. Cut a new underbelly material to fit repair hole. Secured in place with screws and washers. Covered all cuts and screws in underbelly with roof seam tape. Painted all roof seam tape black. Filled gap around plumbing drain outlet with spray foam. Painted all spray foam black.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		DKM	425.00
Z990	MISC LABOUR CODE (EXTERNAL)		DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		DKM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)		DKM	0.00
Parts				
Part #	Description	Qty	Price	Total
3673	1.5" FERNCO COUPLER	2.00	10.99	21.98

24449	3" WASTE VALVE	1.00	15.99	15.99
4351	QUICK ROOF EXTREME - BLACK FOR RV'S	1.00	35.99	35.99

Subtotal for Job #2: 498.96

Parts Total: 73.96
Labour Total: 442.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 515.96

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 12 Nov 2024

W/O: 75115
Promised Date: 30 NOV 24



Customer #: 1000
BASDEN'S AMERICAN RV,


