



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75125



CUSTOMER WORK ORDER

WO #: 75125 (Appointment Date: 18 OCT 2024 - Time: 04:00pm)
Customer: 53914 - ALVAREZ, O.D., MICHAEL - 260-415-0267
Tag:
Author: PH
Location: 1025 CHECK PREAUTH
Stock #: 11305
Stock Desc: (11305) 2024 COACHMEN REMOTE RMT16R
Chassis #: 5ZT2RMEC2RL016638
Serial #: 5ZT2RMEC2RL016638
Mileage:
Licence:
Invoice #: 410986
Date In: 18 OCT 24
Promised:
Date Sched:
Completed: 25 OCT 24
Warr. Date: 13 JUN 24

Job #WINTER - External

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.
INCLUDES 2 GALLONS OF ANTI-FREEZE
UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA
DE-WINTERIZATION IS NOT INCLUDED
NUMBER OF GALLONS USED _____

CAUSE: RAN A.F. THROUGH ALL LINES AND FIXTURES. BYPASSED WATER HEATER. DRAINED ALL TANKS.

CORRECTION: .

Labor				
Code	Description		Mechanic	Total
Z990	WINTERIZE UNIT		ZMS	N/C
Z990	WINTERIZE UNIT		ZMS	N/C
Parts				
Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #SIDET - External

COMPLAINT: EXTERIOR SIDEWALL SEAL INSPECTION. ROOF NOT INCLUDED. 1 TUBE OF SIDEWALL SEALANT INCLUDED.

CAUSE: The compartment doors, front radius trim, rear corner trim, fender skirts and lights all need to be touched up. Tech will need to clean debris off areas and tape off before sealing.

CORRECTION: CLEANED UP SEAMS. LET DRY. TAPED OFF EDGES. SEALED WITH SILICONE AND REMOVED EXCESS. REMOVED TAPE. CLEANED UP AREA.

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		ZMS	N/C
Parts				
Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	N/C	N/C



Customer #: 53914
ALVAREZ, O.D., MICHAEL



Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #SIDET: 0.00

Job #3 - Warranty

COMPLAINT: THE BLACK STRIPS KEEP COMING OFF ON THE FRONT

CAUSE: Removed original I sent trim and mounting screws. Installed new trim 9n both sides. Secured screws and applied dicor to the top where it meets the roof.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	34.00

Parts

Part #	Description	Qty	Price	Total
E369	E369 BLACK HD 1" x 25' INSERT TRIM	1.00	8.53	8.53

Subtotal for Job #3: 42.53

Job #4 - Internal

COMPLAINT: THE FRONT DRIVERS SIDE WINDOW WILL NOT CLOSE ALL THE WAY

CAUSE: Removed screen and inspected window. Window is shutting all the way and is sealing against gasket. There are 2 cutouts in the bottom for weep holes that allow water to drain out of the window if needed.

CORRECTION: No correction.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #4: 0.00

Job #5 - Internal

COMPLAINT: KITCHEN SINK HAS A SLOW LEAK AND DRIPS

CAUSE: Hooked up to city water and pressurized water system. Ran water through hot and cold lines. Leaving the system under pressure to find leak. COULD NOT FIND ANY LEAKS ON FAUCET OR LINES LEADING TO IT.

CORRECTION: NO CORRECTION.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #5: 0.00

Parts Total: 8.53
Labour Total: 34.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 42.53

Customer #: 53914
ALVAREZ, O.D., MICHAEL

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 25 Oct 2024

W/O: 75125



Customer #: 53914
ALVAREZ, O.D., MICHAEL

