

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
BASDEN RV CENTER INC		<b>CLAIM</b>	2148571
DBA AMERICAN RV CENTER		<b>CLAIM ORIGIN</b>	WEB
600 E BASELINE ROAD		<b>ORIGINAL CLAIM ID</b>	
EVANSVILLE, IN 47725		<b>VIN</b>	5ZT2FEUB3SW030317
USA		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$170.00	<b>SITE/WAREHOUSE</b>	320 / 320
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	FET29SE-320
		<b>DEALER RO #</b>	75164
		<b>CLAIM START DATE</b>	12/12/2024
		<b>CLAIM END DATE</b>	01/01/1900

Retail Date of Purchase \_\_\_\_\_ WARRANTY EXPIRATION DATE \_\_\_\_\_

## Claim Line Details

### Labor

<b>Line#</b>	<b>Operation Code</b>	<b>Operational Description</b>		
1	20-66-02-17-000672	Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2024-12-12 12:04:36 :: ENTRY DOOR NEEDS ADJUSTED ENTRY DOOR NEEDS ADJUSTED Removed latch plate from door frame. Filed outer edge of latch plate hole in frame to allow adjustment to plate. Remounted latch plate and checked operation of entrance door. Now closes ok.			
<b>Model#</b>	<b>Dir Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$34.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$34.00
	<b>Notes</b>			

<b>Submitted</b>	Labor Amt	\$34.00	<b>Approved</b>	Labor Amt	\$34.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$34.00		Total	\$34.00

\_\_\_\_\_  
**DEALER** **DATE**  
**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

\_\_\_\_\_  
**CUSTOMER** **DATE**  
**SIGNATURE**

All repairs described have been inspected and are satisfactory.