

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 75170  
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC  
Customer: 54889 - TIMOTHY A. MILLS  
Address: 423 SE 2ND ST EVANSVILLE, IN

47713

Phone: 812-459-1761

Stock Number: 11375 - 2024 DELTA 281BH 7M5TD3122RC303369

VIN: 7M5TD3122RC303369 HIN:

SER#: 7M5TD3122RC303369

Mileage: 0

Work Order Comp: 31 OCT 24

Auth. No:

Dealer #:

Warr. Date: 28 JUN 24

Work Order Date: 23 OCT 24

Inv #: 411286

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
75170	1	THE BLACK TANK FLUSH IS NOT WORKING NOTE: UNIT IS NOT WINTERIZED AND CUSTOMER DECLINED HAVING US WINTERIZE IT AT THIS TIME. Black tank vacuum breaker backwards Hooked up hose to the black tank flush then turned the water on but got nothing to the tank. Checked the backside of the black tank flush connection but no clog. Disconnected the black tank vacuum breaker then connected a ait hose to figure out what water line was the correct line. Inspected further and found that the vacuum breaker put in backwards. Cut the fittings to set in the correct direction then crimped the line back together. Threaded the vacuum breaker back on but didn't function properly, possibly jammed. Went the parts department and got a new vacuum breaker. Installed the new vacuum breaker and tested. Now the black tank flush works as should.	
75170	2	OFF DOOR SIDE FENDER MISSING A RIVIT Rivit was not secured to the j wrap Inspected the off door side fender, found a rivet not holding to the j wrap. Drilled out the rivet then put a new rivet in place but had to drill a new hole because the factory hole was off center from the fender.	
75170	5	CUSTOMER WOULD LIKE TO HAVE THE BATHROOM DOOR CHECKED. IT SEEMS TO BE OUT OF ADJUSTMENT. bathroom entry door not opening and closing properly i tried to get the door to function improperly but could not find	

