

Pre-Authorization

Pre-Authorization number PA03779253 Reference no: 75263 Status: Approved Approved by anglr Approved date 12/4/2024
Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTSGM29S7101136
600 E Baseline Rd
Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2300114A	Entrance Door - H	0.00	0.25	0.20		1	0.20	Complaint:THE ENTRY DOOR WILL NOT LATCH. NOTED ON DELIVERY Cause:ENTRY DOOR WILL NOT LATCH. NOTED ON DELIVERY. Correction:Removed door frame latch plate. Filed edge of cutout in door frame to allow latch plate to adjust and let entry door latch cl;osed. Remounted latch plate and checked operation. Entry door new latching closed. KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.
2	6101315A	Fresh Water Pres	0.00	1.20	1.00		1	0.10	Complaint:WINTERIZED HOSE HAS 2 BENDS IN IT Cause:WINTERIZING HOSE HAS (2) BENDS IN IT. HOSE IS PINCHED FLAT. Correction:Cut off hose past shut off to allow for new hose to be attached with a 90 deg. fitting rto eleminate two bends in hose. Cut new hose to fit and installed with clamps. Checked all hose clamps for leaks. No leaks found. KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual. KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.

Pre-Authorization number PA03779253

1.20For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return toKeystone RV Company