

**Pre-Authorization**

Pre-Authorization number PA03778289 Reference no: 75335 Status: Approved Approved by anglr Approved date 12/3/2024  
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTSGR22R7104351 11/12/2024  
 600 E Baseline Rd  
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	5100306B	Breakaway Switch	0.00	0.80	0.20		1	0.20	Complaint:EMERGENCY BREAKAWAY SWITCH DOES NOT WORK Cause:EMERGENCY BRAKEAWAY SWITCH DOES NOT WORK. Correction:Emergency Brakeaway switch not working when pulled. Checked operation of switch. Points inside switch are not making contact when pulled. Removed factory switch. installed new switch. Checked operation of new switch. Brakes are now locking when switch cord is pulled.  KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only)

Pre-Authorization number PA03778289 0.20

For paper claims only use one pre-authorization number per warranty claim for  
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return toKeystone RV Company