

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 2170330 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 5ZT2RMHC1SL018317 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 224 / 224 <b>ITEM #</b> RMT19R <b>DEALER RO #</b> 75358 <b>CLAIM START DATE</b> 01/13/2025 <b>CLAIM END DATE</b> 01/01/1900
<b>Labor rate:</b> \$170.00 <b>OWNER INFORMATION</b>	

**Retail Date of Purchase** \_\_\_\_\_ **WARRANTY EXPIRATION DATE** \_\_\_\_\_

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b> 60-141-19-00-001596	<b>Operational Description</b> Tub Surround - Plumbing/Shower, Tub Surround/Reseal/No Tread Code
	<b>Complaint, Cause, Correction</b>	
	Original Note : bhoffman@americanrvcenter.com, 2025-01-13 12:14:16 :: SHOWER NEEDS SEALED AT THE TOP Seal around top of shower I first went to lot to find unit then I found and took pictures of where it was not sealed properly and I put more clear silicone on to seal the crack	
<b>Model#</b>	<b>Dlr Sub Hrs</b> 0.20	<b>Sub Labor Amt</b> \$34.00
<b>Serial#</b>	<b>Appr Hrs</b> 0.20	<b>Appr Labor Amt</b> \$34.00
	<b>Notes</b>	

<b>Submitted</b>	Labor Amt	\$34.00	<b>Approved</b>	Labor Amt	\$34.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$34.00		Total	\$34.00

**DEALER** \_\_\_\_\_ **DATE** \_\_\_\_\_  
**SIGNATURE**  
 I certify that I have performed these repairs consistent with Forest River Policies.

**CUSTOMER** \_\_\_\_\_ **DATE** \_\_\_\_\_  
**SIGNATURE**  
 All repairs described have been inspected and are satisfactory.