



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75626
Promised Date:
24 JAN 25

CUSTOMER WORK ORDER

WO #: 75626

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag: DWS - SEE COMMENTS 2-4-25
Author: DWS
Location: 0415 SEE IF BB HAS PUT
DECAL ON THIS YET

Stock #: 11517
Stock Desc: 2025 5W ALLIANCE RV
VALOR 44V14
Chassis #: 7M5FV4637SA010117
Serial #: 7M5FV4637SA010117
Mileage: 0
Licence:

Invoice #:
Date In: 04 DEC 24
Promised: 31 JAN 25
Date Sched:
Completed: 31 MAR 25
Warr. Date:

Job #PDINFW - Internal

Transferred to BAS*75902 on 04 FEB 25
Estimate amount was 0.00
PDI - NEW FIFTH WHEEL

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	GAH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	GAH	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #WINTER - Internal

Transferred to BAS*75902 on 04 FEB 25
Estimate amount was 0.00
WINTERIZE UNIT AND DRAIN HOLDING TANKS.
INCLUDES 2 GALLONS OF ANTI-FREEZE
UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA
DE-WINTERIZATION IS NOT INCLUDED
NUMBER OF GALLONS USED _____

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	GAH	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #1 - Warranty

COMPLAINT: OUTSIDE OFF DOOR SIDE DECAL PEELING

CAUSE: Off doorside rear decal's peeling.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	85.00



Customer #: 1000
BASDEN'S AMERICAN RV,





Parts				
Part #	Description	Qty	Price	Total
26013	Decal - DC 8 Rv1 (Valor 2024)	1.00	5.99	5.99

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-ALL PARTS	1.00	12.12	12.12

Subtotal for Job #1: 103.11

Job #2 - Warranty

COMPLAINT: BENT RAMP CABLE CLIP

CAUSE: Bent ramp cable clip
 Bent locking pin

CORRECTION: Unlocked the rear door and pulled down the door. Pulled off the pin then put on the new pin and closed the door.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	17.00

Parts				
Part #	Description	Qty	Price	Total
18409	18409 Pin - 3/8" x 1 3/4" w/Wire Loc	1.00	2.99	2.99

Subtotal for Job #2: 19.99

Job #3 - Warranty

COMPLAINT: ALL 4 BOLTS FOR REAR BED LIFT SYSTEM ARE LOOSE

CORRECTION: I FOUND THAT THE 4 BOLTS THAT HOLD THE LOCKS FOR BACK REST ON THE REAR BED / HAPPY JACK SYSTEM WERE LOOSE. THEY NEEDED TO BE TIGHTENED UP SO THAT THEY WOULD WORK RIGHT. I TIGHTENED UP THE 4 BOLTS TO THE SLIDE LOCKS TO THE BACK REST AND NOW THE LOCKS WORK AS THEY SHOULD.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	68.00

Subtotal for Job #3: 68.00

Job #4 - Warranty

COMPLAINT: SCREEN ON CENTER A/C THERMOSTAT HAS DAMAGE

CAUSE: Screen on center thermostat has bad spots in it need to repalce the thermostate

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	85.00

Parts				
Part #	Description	Qty	Price	Total
26086	26086 Thermostat - Digital_ - Heat/Co	1.00	29.99	29.99

Subtotal for Job #4: 114.99

Job #5 - Warranty

COMPLAINT: DOOR SIDE REAR AWNING FRONT ARM NEEDS TO BE ADJUSTED

CAUSE: Front awning arm on rear awning needs adjusted arm will not close all the way

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	170.00



Subtotal for Job #5: 170.00

Job #6 - Warranty

COMPLAINT: ADJUST BEDROOM DOOR NOT LATCHING

CORRECTION: I found that the bedroom door would not close. I adjusted the hinges and striker plate.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	34.00

Subtotal for Job #6: 34.00

Job #7 - Warranty

COMPLAINT: GLUE ON BEDROOM MIRROR SLIDING DOOR

CORRECTION: FOUND SMALL SPOTS OF GLUE ON BEDROOM CLOSET DOOR MIRROR. CLEANED GLUE OFF MIRROR.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	17.00

Subtotal for Job #7: 17.00

Job #8 - Warranty

COMPLAINT: MAIN DOOR STEPS ARE RUBBING DOOR JAM

CORRECTION: I FOUND THAT THE STEPS SUPPORTS THAT HOLD THE STEPS UP IN THE DOOR JAM FOR TRAVEL WERE VERY TIGHT IN THE DOOR JAM. I HAD TO ADJUST THE BRACKETS ON THE STEPS SO THAT THEY DONT GET STUCK IN THE DOOR JAM WHEN FOLDED IN.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	34.00

Subtotal for Job #8: 34.00

Job #9 - Warranty

COMPLAINT: HOLE OVER MAIN BED NEXT TO LIGHT NEEDS FILLED

CORRECTION: FOUND A HOLE IN THE CEILING OVER THE MAIN BED IN THE BEDROOM. LOOKS LIKE THE FACTORY MOVED THE LIGHT AND LEFT A SCREW HOLE BEHIND

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	34.00

Subtotal for Job #9: 34.00

Job #10 - Warranty

COMPLAINT: BOTTOM OF SCREEN DOOR ON MAIN DOOR IS COMING APART

CORRECTION: I FOUND THAT THE BOTTOM OF THE SCREEN DOOR WAS FALLING OFF. I PUSHED THE CORNERS BACK IN AND THE DROPPED BACK OUT. I DRILLED HOLES AND ADDED SCREWS TO THE CORNERS TO KEEP THE CORNERS FROM FALLING OUT.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	51.00

W/O: 75626
Promised Date: 31 JAN 25



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #10: 51.00

Job #11 - Warranty

COMPLAINT: BLACK TANK FLUSHERS, 2 ARE MISSING GROMMETS

CAUSE: parts missing

CORRECTION: I FOUND THAT BOTH THE FRONT AND REAR BLACK TANK FLUSHER PORTS WERE MISSING THE GROMMETS. I INSTALLED NEW GROMMETS AND THEY NOW WORK AS THEY SHOULD.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	17.00

Parts

Part #	Description	Qty	Price	Total
10-1211	20183 3-PK 1" HOSE FILTERS	1.00	1.99	1.99

Subtotal for Job #11: 18.99

Job #12 - Warranty

COMPLAINT: LOCKING PINS ON LOWER LEGS ARE NOT CATCHING ON REAR HAPPY JACK SYSTEM.

CAUSE: Locking pens with holding legs in place

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	17.00

Parts

Part #	Description	Qty	Price	Total
25792	25792 Double Snap Button - Legs - Ha	2.00	8.99	17.98

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DOUBLE SNAP PINS	1.00	8.67	8.67

Subtotal for Job #12: 43.65

Parts Total: 58.94
 Labour Total: 629.00
 Sublet Total: 0.00
 Extras Total: 20.79

WORK ORDER TOTAL: 708.73

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 03 Apr 2025

W/O: 75626
Promised Date: 31 JAN 25

Customer #: 1000
BASDEN'S AMERICAN RV,

