

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75663
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 9905 - MICHAEL ELLISON
Address: 8200 OAK GROVE RD NEWBURGH, IN

47630

Phone: 812-598-6710

Stock Number: 11345 - 2024 CATALINA 263BHCKLE 5ZT2CARB8RX030716

VIN: 5ZT2CARB8RX030716 HIN: SER#: 5ZT2CARB8RX030716

Mileage: 0 Work Order Comp: 19 DEC 24

Auth. No: Dealer #:

Warr. Date: 29 FEB 24 Work Order Date: 07 DEC 24 Inv #: 412822

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 9905 - MICHAEL ELLISON
Address: 8200 OAK GROVE RD NEWBURGH, IN
47630
Phone: 812-598-6710
Stock Number: 11345 - 2024 CATALINA 263BHCKLE 5ZT2CARB8RX030716
VIN: 5ZT2CARB8RX030716 HIN: SER#: 5ZT2CARB8RX030716
Mileage: 0 Work Order Comp: 19 DEC 24
Auth. No: Dealer #:
Warr. Date: 29 FEB 24 Work Order Date: 07 DEC 24 Inv #: 412822

WO # Job # Description JOB INFORMATION

75663 1 REAR AWNING ARM NOT CLOSING ALL THE WAY
Rear awning arm not closing all the way
I first ran awning out to loosen the bolts to move the arm over
towards the back of unit to allow it to close properly I then
tightened up bolts and ran the awning back in and it is now
closing properly
75663 2 CHECK BATTERY...CUSTOMER SAYS IS GOING DEAD WITH SOLAR CHARGER
Battery not charging on solar
I inspected battery and then found the pannel for the solar and
it was not turned on I then turned it on and the battery was at
11.6 then after moving it right outside the door it went up to 12
volts

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.30	170.00	51.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	170.00	34.00

Parts Total: 0.00
Labour Total: 85.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 85.00

Customer Signature: _____

Date: _____