



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75675
Promised Date: 24 DEC 24



CUSTOMER WORK ORDER

WO #: 75675 (Appointment Date: 10 DEC 2024 - Time: 09:00am)

Customer: 51858 - WOODASON,
ROBERT - 812-201-5540

Tag:

Author: BJW

Location: 1215 CHECK PREAUTH

Stock #: 11396

Stock Desc: (11396) 2024 COACHMEN

CATALINA 263BHCKLE

Chassis #: 5ZT2CARB1RN300378

Serial #: 5ZT2CARB1RN300378

Mileage:

Licence:

Invoice #:

Date In: 10 DEC 24

Promised: 31 DEC 24

Date Sched:

Completed: 11 DEC 24

Warr. Date: 20 SEP 24

Job #1 - Warranty

COMPLAINT: 24V846, 2024-684 - IMPROPER SOLAR CONTROLLER WIRING
UNIT IS WINTERIZED PER CUSTOMER.

CAUSE: Correct wires

CORRECTION: Took pictures of the solar wires in the correct connection.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	17.00

Subtotal for Job #1: 17.00

Job #2 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE FLAP SEAL AT THE TOP OF THE SLIDE ROOM WILL
NOT FOLD OVER. WE ADJUSTED FOR THIS ON WORK ORDER# 75299 LINE#1. CUSTOMER
ADVISES THAT THE GAP AT THE TOP OF THE ROOM IS VERY TIGHT.

CAUSE: Flap seal didn't flap outward

CORRECTION: Plugged in the shore power then ran the slideroom in and out several times and the flap
seal didn't flip out. Cut some roof tape to 1 inch wide and 6 inches long then stuck to the slideroom roof.
Ran the slideroom in and out several more time and the flap seal flip as it should.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	51.00

Subtotal for Job #2: 51.00

Parts Total:	0.00
Labour Total:	68.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	68.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited
to work performed. Consequential damages are not covered. All guaranteed work
must be completed in our service department.



Customer #: 51858
WOODASON, ROBERT

