

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2173935
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CXKB5SL018503
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	224 / 224
OWNER INFORMATION		ITEM #	AAPT208BHS
		DEALER RO #	75681
		CLAIM START DATE	01/16/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-99-01-00-001014	Mini-Blind or Vertical Patio Blind Wand - Interior/Soft Goods/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-01-16 10:29:04 :: THE WINDOW BLIND OVER THE KITCHEN SINK IS MISSING A ROD Missing blind rod Installed new rod.			
Model#	Dlr Sub Hrs	0.00	Sub Labor Amt	\$0.00
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	30-99-24-00-001011	Curtains - Interior/Soft Goods/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-01-16 10:30:12 :: THE CURTAIN HOLDBACK ON THE UPPER BUNK IS TUCKED UNDER THE TRIM AND STAPLED DOWN. Strap stuck behind trim Removed trim and seen strap had been glued down. Strap is black material with yellow gold stitching and velcro ends. Strap measured 16 in long by 3 in tall.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$85.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
	Notes			

Submitted	Labor Amt	\$85.00	Approved	Labor Amt	\$17.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$85.00		Total	\$17.00

DEALER _____ DATE _____
SIGNATURE _____

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____

All repairs described have been inspected and are satisfactory.