

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 75684
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11516 - 2025 CATALINA SUMMIT SERIES 261BHS 5ZT2CARB8SU044963
VIN: 5ZT2CARB8SU044963 HIN: SER#: 5ZT2CARB8SU044963
Mileage: 0 Work Order Comp: 17 JAN 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 11 DEC 24 Inv #: 413314

WO # Job # Description JOB INFORMATION

75684 1 THE BLACK TANK FLUSH INLET IS MISSING A GASKET
GASKET/SCREEN IS MISSING.
INSTALLED GASKET/SCREEN ON INLET.

75684 2 THE SEALER ON THE WALL BEHIND THE SLIDE ROOM ON THE OUTSIDE IS
NOT SEALING PROPERLY.
THERE IS EXCESS SEALER ON THE WALL BEHIND THE SLIDE ROOM.
APPLIED MINERAL SPIRITS TO THE WALL AND REMOVED WITH A TOWEL.

75684 3 THERE IS A SCRATCH ON THE FLOOR. IT IS IN BETWEEN THE VENT AND
THE ENTERTAINMENT CENTER.
FIBER NEW CAME AND FIXED

75684 4 THE BATTEN STRIPS ABOVE THE SLIDE IN THE BEDROOM ARE LOOSE
The batten strips came loose above the slide room and one in the
bedroom.
Pushed batten strips onto the ceiling.

75684 5 THERE ARE SEVERAL HOLES IN THE CABINETS UNDER THE SINK AND THE
STOVE THAT NEED TO BE FILLED
Staple holes need filled.
Filled holes with putty.

75684 7 THERE IS GLUE ON THE WALL BEHIND THE DINETTE SEAT
GLUE ON WALL.
APPLIED MINERAL SPRIrts AND REMOVED GLUW WITH TOWEL.

Claim : 75684

 WO # Job # Description JOB INFORMATION

75684 8 THERE IS EXCESS SEALER ON THE OUTSIDE REAR WALL. THIS IS ON THE
 TOP ROOF TRIM.
 THERE IS EXCESS SEALER ON THE ROOF TRIM.
 MOVED A LIFT TO THE UNIT. REMOVED SEALER.

75684 9 THE ENTRY DOOR IS HARD TO OPEN
 DOOR IS STICKING WHEN OPENING,
 APPLIED LUBRICANT TO DOOR LATCH. MOVED LATCH OVER SLIGHTLY WITH
 HAMMER.

75684 10 THE TELEVISION WILL NOT PICK UP CHANNELS
 PULLED BOOSTER OFF OF WALL. THE COAX CABLE IS NOT CONNEDCTED TO
 THE BOOSTER. USED HOOK TOOLS TO PULL COAX THROUGH THE CUT OUT.
 HOOKED UP COAX TO BOOSTER AND RAN A CHANNEL SCAN. NO CHANNELS
 WERE FOUND. THE FITTING ON LINE DOESNT LOOK LIKE ITS MAKING A
 GOOD CONNECTION. CUT END OFF. INSTALLED A NEW COAX FITTING. RAN A
 CHANNEL CAN AND TV IS PICKING UP CHANNELS. INSTALLED BOOSTER TO
 WALL.

 Part No Job# Description PARTS Qty Price Total

 CMC20183 1 20183 3-PK 1" HOSE FILTERS 1.00 2.12 2.12

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.10 170.00 17.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.10 170.00 17.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00
 Z990 9 MISC LABOUR CODE (EXTERNAL) 0.20 170.00 34.00
 Z990 10 MISC LABOUR CODE (EXTERNAL) 0.60 170.00 102.00
 Z990 10 MISC LABOUR CODE (EXTERNAL) 0.00 170.00 0.00

 Job# Sublet Description SUBLET Total

 3 FIBER NEW 375.00

Parts Total: 2.12
 Labour Total: 306.00
 Sublet Total: 375.00
 Extras Total: 0.00

>>>> Claim Total: 683.12

Customer Signature: _____

Date: _____